



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8872E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PRIG4 COVER FRONT BUMPER	DEFORMED	499.90	499.90
1	PRIG4 UNIT ASSY HEADLAMP	CUT	3,455.00	3,455.00
1	FENDER SUB-ASSY FRONT RH	TO REPAIR SEE LABOUR	945.30	-
1	SUPPORT FRONT BUMPER SIDE	NOT NECESSARY	82.30	-
1	PRIG4 EMBLEM SIDE PANEL	NECESSARY	86.50	86.50
10	PRIVC BUMPER PIECE	NECESSARY	22.00	22.00
	LESS 25% DISCOUNT		-1,272.75	-1,015.85
			3,818.25	3,047.55
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY FRONT RH.		700.00	320.00
	SPRAYPAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.		50.00	30.00
	TUFF COAT ON AFFECTED PARTS.	NOT NECESSARY	50.00	-
			1,300.00	750.00
	GRAND TOTAL		5,118.25	3,797.55
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			3,050.00

Report Ref No. NS/INC20014033/T1tf3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.