

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014034/T1TD3E2
Date: 14/01/2021

REFERENCE

Insured/Claimant: NG WEI HONG Policy No: 1900165868
Date of Loss: 16/12/2020 Nature of Claim: OD Claim No: 5329160205SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP6183C**
Make & Model: KIA STINGER, 2.0 (A) Engine No: G4KLKH025470
Reg. Date: 04/10/2019 (Man. Year: 2019) Chassis No: KNAE351AML6074590
Colour: Blue Odometer: 12299 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$140,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,208.00	1,676.00	532.00	24.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	2,540.00	1,640.00	39.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,388.00	4,216.00	2,172.00	34.00
+ GST 7.00/7.00% (S\$)	447.16	295.12	152.04	34.00
Nett Amount (S\$)	6,835.16	4,511.12	2,324.04	34.00

INSPECTION

Date of Assignment: 17/12/2020
Date Inspected: 17/12/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*PANEL ASSY-FENDER, RH	Bent	857.00 F	*857.00 FL
3	1		*GUARD ASSY-FRONT WHEEL, RH	Deformed	159.00 F	*159.00 FL
4	1		*WHEEL ASSY-ALUMINIUM	Cut	1,054.00 F	*1,054.00 FL
5	1		*GARNISH ASSY-FENDER RH	Not Necessary	118.00 F	*- FL
					<hr/>	
					Sub Total (\$\$)	2,208.00 2,090.00
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 414.00
					<hr/>	
					Total Parts (\$\$)	2,208.00 1,676.00
					<hr/>	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT FENDER RH, REPAIR FRT BUMPER, SIDE SILL RH	New	1,600.00	800.00
2	SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, SIDE SILL RH	New	2,200.00	1,440.00
3	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
4	TRANSFER RIM	New	30.00	30.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	120.00
Gross Labour Cost (\$\$)			4,180.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >