

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014036/KQD3Q2

Date: 27/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00007682000

Claimant Vehicle No : SDA6337L **Insured Vehicle No :** SMW1939K

Date of Loss: 15/12/2020 **Nature of Claim:** TP **Claim No:** SNM20D204888/C02/CHNGPW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDA6337L		
Make & Model:	BMW 740LI, 3.0 (A)	Engine No:	10778424N55B30A
Reg. Date:	31/05/2013 (Man. Year: 2013)	Chassis No:	WBAYE42050DD87288
Colour:	Metallic Pearl White	Odometer:	184134 km
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R20	Rear Tyre Size:	275/35 R20
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,579.80	7,033.50	15,546.30	68.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,900.00	1,190.00	2,710.00	69.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,479.80	8,223.50	18,256.30	68.94
Approved Total (Overridden) (S\$)		6,550.00		
(S\$)	26,479.80	6,550.00	19,929.80	75.26
+ GST 7.00/7.00% (S\$)	1,853.59	458.50	1,395.09	75.26
Nett Amount (S\$)	28,333.39	7,008.50	21,324.89	75.26

INSPECTION

Date of Assignment: 17/12/2020

Date Inspected: 17/12/2020 Inspected At:

160 SIN MING DRIVE#06-02
Repairer: MBM Wheelpower Pte Ltd
(Sin Ming)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jan 2021)
Parts:	143	BMW 740LI 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDA6337L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	3,200.00 FL	*- FL
2	1		*BONNET FRONT SEAL	Serviceable	97.00 FL	*- FL
3	1		*BONNET WEATHERSTRIP	Serviceable	50.00 FL	*- FL
4	1		*BONNET BMW LOGO	Serviceable	130.00 FL	*- FL
5	1		*FRONT BUMPER	Buckled / Cracked	1,980.00 FL	*1,500.00 FL
6	1		*FRONT BUMPER TOWING COVER	Missing	65.00 FL	*35.00 FL
7	1		*FRONT BUMPER LOWER SPOILER	Serviceable	100.00 FL	*- FL
8	1		*FRONT BUMPER LICENSE PLATE	Dented	110.00 FL	*110.00 FL
9	1		*FRONT BUMPER RUBBER STRIP LH	Serviceable	145.00 FL	*- FL
10	1		*FRONT BUMPER RUBBER STRIP RH	Serviceable	145.00 FL	*- FL
11	1		*FRONT BUMPER SENSOR	Torn	460.00 FL	*260.00 FL
12	10		*FRONT BUMPER CLIP	Necessary	100.00 FL	*100.00 FL
13	1		*FRONT BUMPER SPONGE	Serviceable	130.00 FL	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Repair	900.00 FL	*- FL
15	1		*FRONT BUMPER LOWER CENTER GRILLE	Dented	90.00 FL	*90.00 FL
16	1		*FRONT BUMPER SIDE GRILLE LH	Serviceable	90.00 FL	*- FL
17	1		*FRONT BUMPER SIDE GRILLE RH	Missing	90.00 FL	*90.00 FL
18	1		*FRONT GRILLE LH	Cracked	200.00 FL	*165.00 FL
19	1		*FRONT GRILLE RH	Cracked	200.00 FL	*165.00 FL
20	1		*FOG LAMP LH	Serviceable	300.00 FL	*- FL
21	1		*FOG LAMP RH	Serviceable	300.00 FL	*- FL
22	1		*HEADLAMP LH	Serviceable	6,500.00 FL	*- FL
23	1		*HEADLAMP RH	Cracked	6,500.00 FL	*5,250.00 FL
24	1		*FRONT FENDER LH	Repair	1,220.00 FL	*- FL
25	1		*FRONT FENDER INNER SHIELD LH	Serviceable	200.00 FL	*- FL
26	1		*FRONT FENDER RH	Repair	1,220.00 FL	*- FL
27	1		*FRONT FENDER INNER SHIELD LH	Serviceable	200.00 FL	*- FL
28	20		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	200.00 FL	*- FL
29	1		*FRONT NUMBER PLATE & HOLDER	Necessary	100.00 FS	*45.00 FS
30	1		*BODY SEALANT ON BONNET	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,072.00	7,810.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,492.20	776.50
Total Parts (\$\$)	22,579.80	7,033.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,800.00	500.00
2	TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	100.00	0.00
3	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	150.00	30.00
4	TO REMOVE & REFIT ALL SENSOR	New	100.00	60.00
5	TO RESET ENGINE WARNING LIGHT (ABS ,SRS ,ECU MEMORY & ETC)	New	150.00	100.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,600.00	500.00
Gross Labour Cost (S\$)			3,900.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >