

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20014039/T1QD3E2

Date: 25/01/2021

REFERENCE

Insured/Claimant:	SREEJITH SATHIANATHAN	Policy No:	1900099733	
Date of Loss:	16/12/2020	Nature of Claim:	OD	Claim No: 2473289534SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML5045X	Engine No:	G4FGJH720990
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5038719
Reg. Date:	24/05/2019 (Man. Year: 2019)	Odometer:	16469 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,402.80	856.00	2,546.80	74.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	2,890.00	920.00	24.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,212.80	3,746.00	3,466.80	48.06
+ GST 7.00/7.00% (S\$)	504.90	262.22	242.68	48.06
Nett Amount (S\$)	7,717.70	4,008.22	3,709.48	48.06

INSPECTION

Date of Assignment:	17/12/2020	
Date Inspected:	17/12/2020	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*PANEL ASSY-TRUNK LID	Repair	1,297.00 FL	*- FL
4	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
5	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
6	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Not Necessary	25.00 FL	*- FL
7	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Not Necessary	31.00 FL	*- FL
8	1		*STAY-RR BUMPER LH	Not Necessary	65.00 FL	*- FL
9	1		*STAY-RR BUMPER RH	Not Necessary	65.00 FL	*- FL
10	1		*ANTENNA ASSY-SMARTKEY	Not Necessary	46.00 FL	*- FL
11	1		*BEAM-RR BUMPER	Not Necessary	318.00 FL	*- FL
12	2		*BRACKET-RR BEAM LWR MTG	Not Necessary	12.00 FL	*- FL
13	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	6.00 FL	*- FL
14	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
15	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
16	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
17	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 FL	*- FL
18	1		*LAMP ASSY-SIDE T/SIGNAL, RH	Not Necessary	181.00 FL	*- FL
19	1		*COVER-RR BUMPER FOG LAMP, LH	Not Necessary	19.00 FL	*- FL
20	1		*COVER-RR BUMPER FOG LAMP, RH	Not Necessary	19.00 FL	*- FL
21	2		*GROMMET ASSY-SCREW	Not Necessary	4.00 FL	-
22	10		*CLIP	Necessary	10.00 FL	*10.00 FL
23	1		*COVER-RR BUMPER	Deformed	651.00 FL	*651.00 FL
24	1		*COVER-RR BUMPER LWR	Deformed	241.00 FL	*241.00 FL
25	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
26	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
27	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
28	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
29	1		*COVER-RR BUMPER UNDER, LH	Deformed	33.00 FL	*33.00 FL
			(Supplementary)			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,231.00	1,055.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	828.20	199.00
Total Parts (\$\$)	3,402.80	856.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BOOT LID, REAR BUMPER FACE, REPAIR REAR END PANEL	New	1,600.00	1,200.00
2	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
3	PAINT WORK SPRAY REAR END PANEL, REAR BOOT LID, REAR BUMPER FACE AND AFFECTED PORTION	New	1,920.00	1,440.00
4	PERFORM RUST PREVENTION	New	80.00	40.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (\$\$)			3,810.00	2,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >