

## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

## **ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV09893/SREEJITH SATHIANATHAN			
	Reg No/Reg Date	SML5045X / 24/05/201			
	Date In/Mileage				
	Chassis No	KNAF3416MK5038719			
	The second secon	G4FGJH720990			
	Make/Model	KIA/CERATO 1.6 A SX SR G518			
		CR5 RUNWAY RED / WK SATURN BLACK			

1 A V A A A A A A A A A A A A A A A A A	s Date/Time Pr	inted CSE	Oper	ator		WIP No		
LAX00000 Cred	it 17/12/2020/	11:40 QUD	247	DonBong		25929		
	Description	of Goods / Sen	rices		Qty	Unit Pric	o Disco	/ A
E PNT88000  REMOVE AND INS PNT98000  PAINT WORK SPRA	DAMAGED PARTS ( CE, REPAIR REAR FALL PARKING ASS AY REAR END PANE CE AND AFFECTED	ON REAR BOOT END PANEL SIST	LID, 400		uty	Unit Pric	e Discy	60.00 144° 1920.00 40° 80.00
CHECK WIRING AND 10028901 TO CARRY OUT DIUSING HI-SCAN POSUNDRY	D CHASSIS ELECT AGNOSTIC CHECK RO TEST	RICAL SYSTEM	PRO TEST	na	te			30.00
SUPPLY C&C LOGO SUNDRY SUNDRIES							,	20.00
PANEL ASSY-TRUN LOGO ASSY-KIA S EMBLEM-CERATO BRACKET ASSY-RR BRACKET-ASSY RR STAY-RR BUMPER I STAY-RR BUMPER I ANTENNA ASSY-SM/ BEAM-RR BUMPER BRACKET-RR BEAM BRACKET-RR BEAM BRACKET-RR BEAM BRACKET-RR BEAM	BPR SIDE UPR,L BPR SIDE UPR,R H RH RH RTKEY LWR MTG LWR,CTR				1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	28.00 25.00 31.00 65.00 65.00 46.00 318.00 6.00	20.00 20.00 20.00 20.00 20.00 20.00 20.00	7 1037.60 25.60 22.40 20.00 24.80 52.00 36.80 254.40 9.60 4.80 7.20 7.20

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



## CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

## **ESTIMATE**

Invoice Name & Address	GST Reg No : MR- Owner Name & Vehicle Info				
AIG Asia Pacific Insurance Pte.	Cust No/Name	LCV09893/SREEJITH SATHIANATHAN			
Ltd.	Reg No/Reg Date	SML5045X / 24/05/201			
MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16	Date In/Mileage				
AIG BUILDING	The state of the s	KNAF3416MK5038719			
SINGAPORE 079120		G4FGJH720990			
Contact No 64191000		KIA/CERATO 1.6 A SX SR G518			
		CR5 RUNWAY RED / WK SATURN BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	17/12/2020/ 11:40	QUD	247 / DonBong		25929		
M LAMP ASS	V CIDE T	Description of Good	s / Services		Qty	Unit Price	Disc%	Amount
M LAMP ASS	A-SIDE T	SIGNAL,LH SIGNAL,RH			1.00	181.00	The second second	
M COVER-RR	RIMPED E	OG LAMP, LH			1.00	181.00		
M COVER-RR	BUMPER F	OG LAMP, RH			1.00		20.00	₹15.
M GROMMET	ASSY-SCRE	W LAMP, KH			1.00		20.00	× 15.
M CLIP	TOO! SOIL	"			2.00		20.00	her 3.
COVER-RR	BUMPER				10.00	1.00	20.00	nel - 8.
1 COVER-RR		WR			1.00	651.00		520.
ULTRASONI	IC SENSOR	ASSY-BWS			1.00	241.00		192.
ULTRASONI	C SENSOR	ASSY-BWS			1.00	163.00		× C 130.
ULTRASONI	C SENSOR	ASSY-BWS	F [	7	1.00	163.00	20.00	× 130.4
ULTRASONI	C SENSOR	ASSY-BWS	255	ima	1.00	163.00 163.00		7 130.4
			5111	110012	17170)	103.00	20.00	130.4
			26		114(5			
				1/8	12.16-2 400			
		SURVE	YOR NAME:	Taughth	4799747			
		SLIDVE	YOR SIGNAT	, 1.	un		- 1	
		SURVE		1 /				
		DATE:	(+)	12/20 @ 121	5			
			41	+ in horise	F ' 1/2			
		REMAR	KS:	or justice	Ex: Hbg			
			Resum 1	spore panto	05 den			
			0 ;	7	1			
			fourthe	C Whants. wn				
		1100						
		LKK Auto Consult	ants hence no	otify				
		the Repairer of the	e following:					
		To resurvey before/a     To display damaged	fter spray paintin	ng				
nfin 0		To display damaged     Parts prices are subj	part(s) during res	survey				
onfirm & acc	epted by	Third party survey is     No illegal modification.	on a "Without De	oludios" hasta				
		ivo megai modificatio	n(s) is allowed					
		<ul> <li>Supplementary item/s</li> </ul>	must be seem	veyed and	7% CCT	Nett		7,186.4
		is subject to final app	roval from Insura	ince Company	7% GST on	7186.40		503.0
		Acknowledged by Repa			Total	Davahl-		7
thorized etc	anatony as	id company tstamp	mer —		iocai	Payable Payable		7,689.4
THE STATE OF THE S	gnatury ar	iu company stamp						

m date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any auditional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.