

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20014041/UVF3E2

**Date:** 19/03/2021

### REFERENCE

Insured/Claimant: LAU PUAY CHENG Policy No: 1900142837  
Date of Loss: 11/12/2020 Nature of Claim: OD Claim No: 0443710841SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBQ100G**  
Make & Model: AUDI Q7, 2.0 TFSI QU (A) Engine No: CYR074740  
Reg. Date: 16/08/2019 (Man. Year: 2018) Chassis No: WAUZZZ4M1KD003299  
Colour: White Odometer: 23375 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$215,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 255/55R19 Rear Tyre Size: 255/55R19  
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm  
Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,908.00	2,652.80	5,255.20	66.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,252.00	1,052.00	2,200.00	67.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,160.00</b>	<b>3,704.80</b>	<b>7,455.20</b>	<b>66.80</b>
<b>- Excess (S\$)</b>	<b>500.00</b>	<b>500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>10,660.00</b>	<b>3,204.80</b>	<b>7,455.20</b>	<b>69.94</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>746.20</b>	<b>224.34</b>	<b>521.86</b>	<b>69.94</b>
<b>Nett Amount (S\$)</b>	<b>11,406.20</b>	<b>3,429.14</b>	<b>7,977.06</b>	<b>69.94</b>

### INSPECTION

Date of Assignment: 17/12/2020  
Date Inspected: 17/12/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR UPPER BUMPER	Repair	1,215.00 FS	*- FS
2	1		*REAR LOWER BUMPER	Dented/Deformed	1,681.00 FS	*1,344.80 FS
3	1		*REAR BUMPER FIXING PARTS	Not Necessary	205.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Dented/Deformed	1,247.00 FS	*997.60 FS
5	1		*REAR BUMPER SPOILER TRIM	Not Necessary	105.00 FS	*- FS
6	1		*REAR BUMPER CARRIER	Not Necessary	1,341.00 FS	*- FS
7	2		*REAR BUMPER CARRIER SEAL-LH/RH	Not Necessary	28.00 FS	*- FS
8	1		*REAR BUMPER HOLDING STRAP	Not Necessary	180.00 FS	*- FS
9	1		*REAR BUMPER GUIDE SECTION-CENTRE	Not Necessary	140.00 FS	*- FS
10	2		*REAR PARKING AID SENDOR-INNER/OUTER	Not Necessary	484.00 FS	*- FS
11	4		*REAR PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
12	1		*TAIL LIGHT-RH	Not Necessary	355.00 FS	*- FS
13	2		*REAR WHEEL COVER-LH/RH (GLUE TYPE)	Necessary	388.00 FS	*310.40 FS
14	1		*EXHAUST TAIL PIPE TRIM-RH	Not Necessary	325.00 FS	*- FS
15	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)      7,908.00      2,652.80**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	New	1,350.00	500.00
3	TO RESPRAY REAR BUMPER	New	1,350.00	-
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
			<b>Gross Labour Cost (\$)</b>	<b>3,252.00</b>
				<b>1,052.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >