Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20014042/KTF3Q2

Date: 01/02/2021

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd ML000127 Policy No: Claimant SMW7224A Insured Vehicle No: SLM5325U

Vehicle No:

Date of Loss: Nature of Claim: TP 12/12/2020 Claim No: M2006187

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMW7224A Reg No:

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2G95223

Reg. Date: 03/12/2020 (Man. Year: 2020) Chassis No: JTDKB3FU703092009

Colour: Metallic Pearl White Odometer: 2426 km

Engine Capacity: 1798 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm Front Right Side: Dunlop 9 mm Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,611.97	1,099.80	3,512.17	76.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,990.00	970.00	9,020.00	90.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,601.97	2,069.80	12,532.17	85.83
+ GST 7.00/7.00% (S\$)	1,022.14	144.89	877.25	85.82
Nett Amount (S\$)	15,624.11	2,214.69	13,409.42	85.83

INSPECTION

17/12/2020 Date of Assignment:

Date Inspected: 15/12/2020 Inspected At: Trans-Cab Services Pte Ltd (HQ)

2 Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 3.0 days

Manager: DENISE TAY KWEE CHENG Adjuster: KENNETH KONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Reference				
Part Source	: MRM-SG	Version: 1.0 (Last Synchronised: 15 Jan 2021)		
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SMW7224A)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*COVER,REAR BUMPER	Cracked	485.60 FL	-	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY,REAR BUMPER	Bent	332.70 FL	-	*332.70 FL
3	1		*COVER,REAR BUMPER,LOWER	Dented	22.00 FL	-	*22.00 FL
4	1		*GUARD,REAR BUMPER CENTER	Bent	374.50 FL	-	*374.50 FL
5	1		*REFLECTOR ASSY,REFLEX,RH	Cracked	39.00 FL	-	*39.00 FL
6	1		*RETAINER,REAR BUMPER SIDE,LH	Serviceable	132.60 FL	-	*- FL
7	1		*FILLER,REAR BUMPER EXTENSION,LH	Serviceable	123.70 FL	-	*- FL
8	1		*RETAINER,REAR BUMPER SIDE,RH	Cracked	132.60 FL	-	*132.60 FL
9	1		*SEAL,REAR BUMPER SIDE,LH	Serviceable	118.30 FL	-	*- FL
10	1		*SEAL,REAR BUMPER SIDE,RH	Serviceable	118.30 FL	-	*- FL
11	1		*PANEL SUB-ASSY,QUARTER,RH	Repair	871.50 FL	-	*- FL
12	1		*PANEL SUB-ASSY,BODY LOWER BACK	Repair	651.00 FL	-	*- FL
13	1		*LENS & BODY,REAR COMBINATION LAMP,RH	Serviceable	339.60 FL	-	*-FL
14	1		*LENS & BODY,REAR COMBINATION LAMP,NO 2 RH	Serviceable	261.00 FL	-	*- FL
15	1		*COVER,FLOOR UNDER NO 1 (LH)	Serviceable	175.10 FL	-	*- FL
16	1		*COVER,FLOOR UNDER NO 2 (RH)	Serviceable	241.90 FL	-	*- FL
17	1		*COVER,REAR FLOOR (CTR)	Serviceable	229.90 FL	-	*- FL
18	1		*SET PARKING AID	Serviceable	700.00 FS	=	*- FS
19	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	-	*60.00 FS
20	1		*REAR BUMPER PROTECTOR	No such part	180.00 FS	-	*- FS
21	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	-	*- FS
22	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	-	*- FS
F=Fra	anchise	part. S=	SpcNett. L=ListItemDisc.		-		
	Sub Total (S\$)		•	1,446.40			
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,162.33	346.60		
				Total Parts (S\$)	4,611.97		1,099.80

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	60.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,200.00	400.00
3	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
5	TO REMOVE AND REFIT ELECTRICAL WIRING,BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
6	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
7	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
8	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
11	TOWING FEES	New	150.00	0.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	440.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
15	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
16	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	220.00	0.00
17	TO REPLACE,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
18	TO LIFT-UP/OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
19	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS- MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	-
20	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
	Gross Labour	Cost (S\$)	9,990.00	970.00
	Report was unsubmitted during	a this print-out		
	Troport was ansasmitted during	g and print out.		

< END OF ESTIMATES >