

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20014045/KQD3Q2
Date: 29/06/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004132000
Claimant Vehicle No :	SLS2737C	Insured Vehicle No :	SME8937P
Date of Loss:	12/11/2020	Nature of Claim:	TP
		Claim No:	SNM20D204697/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS2737C		
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Engine No:	LEB5953376
Reg. Date:	15/09/2017 (Man. Year: 2017)	Chassis No:	RU31253362
Colour:	Metallic Grey	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	54,061.52	32,445.62	21,615.90	39.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,060.00	6,320.00	3,740.00	37.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	64,121.52	38,765.62	25,355.90	39.54
Approved Total (Overridden) (S\$)		30,500.00		

Nett Amount (S\$)**64,121.52****30,500.00****33,621.52****52.43**INSPECTION

Date of Assignment: 23/12/2020

Date Inspected: 17/12/2020

Estimated Period of Repair: 28.0 days

Inspected At:

BLK 5038 ANG MO KIO INDUSTRIAL PARK 2
Repairer:Lian Her Motors (HQ)**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS2737C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL-GATE ASSY	Bent	1,350.60 FL	*1,100.90 FL
2	1		*REAR TAIL-GATE GLASS	Shattered	1,256.30 FL	*1,256.30 FL
3	2		*REAR TAIL-GATE SIDE GARNISH	Missing	214.20 FL	*214.20 FL
4	1		*REAR TAIL-GATE GLASS CENTRE GARNISH	Missing	155.60 FL	*155.60 FL
5	1		*REAR TAIL-GATE GLASS MOULDING	Necessary	105.20 FL	*105.20 FL
6	1		*REAR TAIL-GATE TOP SPOILER	Missing	475.10 FL	*475.10 FL
7	1		*REAR THIRD BRAKE LIGHT	Missing	205.10 FL	*205.10 FL
8	1		*REAR TAIL-GATE OUTER GARNISH	Cracked	385.60 FL	*385.60 FL
9	2		*REAR TAIL-GATE HINGE	Distorted	130.20 FL	*130.20 FL
10	2		*REAR TAIL-GATE DAMPER	Bent / Distorted	210.20 FL	*210.20 FL
11	1		*REAR WIPER MOTOR	Serviceable	425.10 FL	*- FL
12	1		*REAR WIPER ARM	Serviceable	155.60 FL	*- FL
13	1		*REAR TAIL-GATE EMBLEM H	Necessary	45.10 FL	*45.10 FL
14	1		*REAR TAIL-GATE EMBLEM VEZEL	Necessary	50.20 FL	*50.20 FL
15	1		*REAR TAIL-GATE OUTER GARNISH	Cracked	385.60 FL	*385.60 FL
16	1		*REAR TAIL-GATE INNER LOCK	Jammed	285.60 FL	*285.60 FL
17	1		*REAR TAIL-GATE INNER TRIM BOARD	Cracked	455.90 FL	*455.90 FL
18	2		*REAR TAIL-GATE LAMP ASSY	Cracked	850.60 FL	*728.00 FL
19	2		*REAR NO PLATE LAMP	Cracked	130.20 FL	*130.20 FL
20	2		*REAR TAIL-LAMP ASSY	Broken	1,711.80 FL	*1,366.40 FL
21	1		*REAR BOOT RUBBER (50%)	Cut	180.64 FS	*112.90 FS
22	1		*REAR END PANEL	Bent	455.10 FL	*455.10 FL
23	1		*REAR END PANEL INNER GARNISH	Dented	185.90 FL	*185.90 FL
24	1		*REAR BUMPER	Missing	955.60 FL	*762.70 FL
25	2		*REAR SIDE BUMPER	N/S Missing / O/S Cracked	671.20 FL	*550.00 FL
26	2		*REAR BUMPER SIDE RETAINER	Cracked	76.40 FL	*76.40 FL
27	2		*REAR BUMPER REFLECTOR	Missing	274.20 FL	*274.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	1		*REAR BUMPER LOWER COVER	Distorted / Cracked	175.20 FL	*175.20 FL
29	1		*REAR BUZZER	Serviceable	185.20 FL	*- FL
30	2		*REAR FENDER	Bent	2,371.80 FL	*1,862.00 FL
31	2		*REAR FENDER AIR DUCT	Dented / Distorted	310.20 FL	*310.20 FL
32	1		*REAR FENDER INNER PANEL	N/S Bent	1,310.20 FL	*655.10 FL
33	2		*REAR FENDER INNER TRIM BOARD	Cracked	850.20 FL	*850.20 FL
34	2		*REAR FENDER ARCH PROTECTOR	Distorted / Cracked	350.40 FL	*350.40 FL
35	2		*REAR FENDER INNER SHIELD	Torn	211.20 FL	*211.20 FL
36	2		*REAR FENDER INNER TOP GARNISH	Distorted	230.40 FL	*230.40 FL
37	1		*REAR O/S FENDER TRIANGLE GARNISH	Missing	95.70 FL	*95.70 FL
38	1		*REAR BOOT TOP COVER	Distorted	355.60 FL	*355.60 FL
39	1		*ROOF LINING	Deformed	839.60 FL	*839.60 FL
40	4		*ROOF AIR BAG SENSOR	Necessary	790.80 FL	*790.80 FL
41	1		*AIR BAG CONTROL UNIT	Necessary (1 PCS ONLY)	2,501.40 FL	*1,250.70 FL
42	2		*REAR DOOR ASSY	O/S Bent	935.10 FL	*935.10 FL
43	2		*REAR DOOR INNER LOCK	Repair	511.20 FL	*- FL
44	1		*REAR DOOR RUBBER	O/S Cut	350.20 FL	*175.10 FL
45	1		*REAR O/S DOOR INNER TRIM BOARD	Mtg Cracked	620.20 FL	*620.20 FL
46	1		*REAR O/S DOOR GLASS REGULATOR MOTOR	Distorted	378.20 FL	*378.20 FL
47	2		*REAR DOOR PILLAR WEATHERSTRIP	Dented (1 PCS ONLY)	330.20 FL	*165.10 FL
48	1		*REAR O/S ROCKER PANEL	Bent	655.50 FL	*655.50 FL
49	1		*REAR O/S ROCKER PANEL GARNISH	Cracked	487.60 FL	*487.60 FL
50	2		*REAR DOOR STEP GARNISH	Serviceable	150.20 FL	*- FL
51	1		*REAR SPARE TYRE PANEL	Bent	1,255.80 FL	*1,255.80 FL
52	1		*REAR SPARE TYRE TOOL SPONGE	Cracked	275.60 FL	*275.60 FL
53	1		*REAR SPARE TYRE TOP COVER BOARD	Distorted	385.60 FL	*385.60 FL
54	1		*REAR EXHAUST SILENCER	Repeated	975.10 FL	*- FL
55	1		*REAR AXLE ASSY	Bent	1,490.70 FL	*1,490.70 FL
56	2		*REAR SHOCK ABSORBER	Bent	770.20 FL	*770.20 FL
57	2		*REAR SHOCK ABSORBER MOUNTING	Bent	310.20 FL	*310.20 FL
58	1		*REAR HUB ASSY	O/S Bent	610.60 FL	*305.30 FL
59	2		*REAR ABS PUMP	Serviceable	510.20 FL	*- FL
60	2		*REAR ABS WIRE SENSOR	Serviceable	391.40 FL	*- FL
61	1		*HYBRID BATTERY (LOCAL REPAIR)	Dented	11,964.00 FS	*3,500.00 FS
62	1		*HYBRID BATTERY CHROME COVER	Dented	325.70 FL	*325.70 FL
63	1		*HYBRID BATTERY FAN DISCHARGE MOTOR	Serviceable	750.70 FL	*- FL
64	1		*HYBRID BATTERY AIR DISCHARGE HOSE	Serviceable	485.10 FL	*- FL
65	1		*HYBRID BATTERY CONTROL UNIT	Serviceable	1,985.20 FL	*- FL
66	1		*HYBRID BATTERY TRAY	Serviceable	256.90 FL	*- FL
67	1		*FUEL TANK	Dented	985.70 FL	*985.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
68	1		*FUEL TANK TUBE	Serviceable	225.10 FL	*- FL
69	1		*FUEL TANK LOCK	Repair	187.20 FL	*- FL
70	1		*FUEL TANK OUTER DOOR COVER	Repair	185.70 FL	*- FL
71	1		*FUEL PUMP ASSY	Serviceable	633.80 FL	*- FL
72	1		*REAR EXHAUST SILENCER	Bent	975.60 FL	*975.60 FL
73	2		*REAR EXHAUST SILENCER HOOK	Distorted	170.20 FL	*170.20 FL
74	1		*REAR EXHAUST SILENCER HEAT SHIELD	Bent	165.20 FL	*165.20 FL
75	1		*FRONT O/S SHOCK ABSORBER	Serviceable	550.75 FL	*- FL
76	1		*FRONT O/S SHOCK ABSORBER MOUNTING	Serviceable	165.20 FL	*- FL
77	1		*FRONT O/S SHOCK ABSORBER LINKAGE	Serviceable	85.70 FL	*- FL
78	1		*FRONT O/S KNUCKLE ARM	Bent	405.70 FL	*405.70 FL
79	1		*FRONT O/S KNUCKLE BEARING	Necessary	195.20 FL	*195.20 FL
80	1		*FRONT O/S HUB ASSY	Serviceable	485.70 FL	*- FL
81	1		*FRONT O/S ABS SENSOR	Serviceable	187.20 FL	*- FL
82	1		*FRONT O/S LOWER ARM	Distorted	425.60 FL	*425.60 FL
83	1		*FRONT O/S DRIVER SHAFT	Repair	955.30 FL	*- FL
84	4		*ROOT AIR BAG	Burst	3,822.00 FS	*3,822.00 FS
85	1		*FRONT & REAR O/S TYRE RIM	Rear O/S Bent	900.00 FS	*450.00 FS
86	1		*TYRES (80%)	Rear O/S Cut	600.00 FS	*160.00 FS
87	1		*REAR TAIL-GATE GLASS SEALANT	Necessary	55.00 FS	*40.00 FS
88	1		*REAR REVERSE CAMERA	Missing	300.00 FS	*300.00 FS
89	1		*REAR REVERSE SENSOR	Torn	200.00 FS	*200.00 FS
90	1		*SUNDRY EXPENES	Not Necessary	60.00 FS	*- FS
91	1		*REAR NO PLATE	Serviceable	40.00 FS	*- FS
92	1		*REAR CCTV	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	62,933.99	38,410.80
- List Item Discount on L Items 20.00/20.00% (\$)	8,872.47	5,965.18
Total Parts (\$)	54,061.52	32,445.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE /RENEW THE ABOVE PARTS INCLUDING KNOCKING ,WELDING & CUTTING	New	2,800.00	2,400.00
2	TO PUTTY AND SPRAY PAINT	New	2,000.00	1,800.00
3	CHECK & RECONNECT WIRING	New	480.00	100.00
4	TO REPSRAY ANTI-RUST PROOFING TREATMENT	New	240.00	210.00
5	REMOVE /REFIT REAR WINDSCREEN TO FACILITATE REPAIR	New	120.00	120.00
6	REMOVE/REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR	New	150.00	60.00
7	REMOVE/RENEW REAR EXHAUST SILENCER	New	120.00	80.00
8	REMOVE/REFIT REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	150.00	100.00
9	REMOVE/RENEW REAR AND REAR UNDERCARRIAGES	New	650.00	220.00
10	CHECK AND REALIGN WHEEL ALIGNMENT	New	80.00	60.00
11	DIAGNOSTIC CHECK ON REAR ABS AND TO RESET SAME	New	200.00	0.00
12	REMOVE/RENEW HYBRID BATTERY AND TO RESET FACTORY SPECIFICATION	New	800.00	360.00
13	REMOVE/REPAIR REAR CUSHION SEAT FRAME AND LEATHER	New	1,000.00	350.00
14	TROILING TOWING	New	150.00	120.00
15	REMOVE /RENEW ROOF LINING ,AIR BAG AND RESET SAME	New	800.00	280.00
16	REMOVE/RENEW FUEL PUMP AND TANK ETC	New	320.00	60.00
Gross Labour Cost (\$\$)			10,060.00	6,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >