#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/III20014047/KQD3E2

Date:

05/01/2021

REFERENCE

Handling Insurer:

India International Insurance Pte Ltd

**Claimant Vehicle No** 

SGR5247U

Policy No: Insured Vehicle No:

GBF787H

R18A1725614

RN61022612

258910 km

Date of Loss:

15/12/2020

Nature of Claim:

ΤP

Engine No:

Chassis No:

Odometer:

Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SGR5247U

Make & Model: Reg. Date:

HONDA STREAM, 1.8 (A) 09/02/2007 (Man. Year: 2006)

Colour:

White

**Engine Capacity:** Market Value/New Car Price: 1799 cc N/A

Sum Insured (S\$):

Market Value/New Car Price

Yes

CREMAX 8 mm

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Front Right Side:

Steering (Serviceable): **Engine Modification:** 

Yes Nο

Footbrake (Serviceable): Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

215/45 R17 Front Left Side: CREMAX 8 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/45 R17 CREMAX 8 mm

CREMAX 8 mm

The above values represent the remaining tyre treads depth

1,858.80	970.48	000.00	4= =0
	010.10	888.32	47.79
0.00	0.00	0.00	
2,080.00	440.00	1,640.00	78.85
0.00	0.00	0.00	
0.00	0.00	0.00	
3,938.80	1,410.48	2,528.32	64.19
	1,100.00		
3,938.80	1,100.00	2,838.80	72.07
	2,080.00 0.00 0.00 3,938.80	2,080.00 440.00 0.00 0.00 0.00 0.00 3,938.80 1,410.48 1,100.00	2,080.00       440.00       1,640.00         0.00       0.00       0.00         0.00       0.00       0.00         3,938.80       1,410.48       2,528.32         1,100.00

<u>INSPECTIO</u>N

Date Inspected:

Date of Assignment:

17/12/2020

21/12/2020

Inspected At:

Messrs V8 Motor Werkz Pte Ltd (HQ)

Blk 7 Sector C, #01-92, Sin Ming Industrial Estate

Singapore 575642

Estimated Period of Repair:

2.0 days

Adjuster: KENNETH KONG Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Jan 2021)

Parts: M1-MPV HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGR5247U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF

ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	788.90 FL	*665.40 FL
2	2		*REAR BUMPER LOWER BRACKET L/R	Serviceable	110.00 FL	*-FL
3	1		*REAR BUMPER SIDE RETAINER L/R	N/S Distorted	125.00 FL	*62.50 FL
4	1		*REAR BUMPER TOW HOOK COVER	Serviceable	13.50 FL	*-FL
5	1		*REAR LH TAILLAMP	Cracked	820.00 FL	*385.20 FL
6	1		*REAR TAILGATE H LOGO EMBLEM	Not Necessary	21.90 FL	*-FL
7	1		*REAR END PANEL	Repair	306.70 FL	*-FL
8	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS
9	1		*SET REAR LH TAILLAMP CLIPS	Necessary	30.00 FS	*30.00 FS
F=Fra	ınchise	e part. S=SpcNe	tt. L=ListItemDisc.	_		
				Sub Total (S\$)	2,296.00	1,193.10
	- List Item Discount on L Items 20.00/20.00% (S\$)		437.20	222.62		
				Total Parts (S\$)	1,858.80	970.48

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR	New	80.00	20.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	200.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	220.00
	Gross Labour Co		2,080.00	440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >