



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2104199

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 14/06/2021
Reference CC4/FCI20014050/R1ea3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLG 6352R
Insured Veh. SHC 7578T
Claim No. D20005136MFSH
Policy No. D-20094921MFSH
Accident Date 14/12/2020
Inspection Date 18/12/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20014050/R1ea3q2	
			Date: 14/06/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7578T	Veh. Inspected	SLG 6352R	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20005136MFSH	Excess (\$)	0.00	
Assign From	ERIC WOO	Assign Date	17/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN GOLF 1.4 TSI AT	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WWWZZZAUZHW057969	Colour	WHITE	
Odometer	52901 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40Z R18	PIRELLI	6 mm	
L/H Front Tyre	225/40Z R18	PIRELLI	6 mm	
R/H Rear Tyre	225/40Z R18	PIRELLI	6 mm	
L/H Rear Tyre	225/40Z R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/12/2020	Inspection Date	18/12/2020	
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			13 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 6352R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED (SN)	DEFORMED	1,158.63	1,158.63
1	RETAINER FOR SPOILER SATI (SN)	SERVICEABLE	188.11	-
1	SET SENSOR BRACKETS PRI (SN)	NECESSARY	21.89	21.89
1	SENSOR BRACKET (SN)	NECESSARY	14.21	14.21
2	SENSOR BRACKET (SN)	NECESSARY	28.42	28.42
1	SENSOR BRACKET (SN)	NECESSARY	14.21	14.21
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	75.94	75.94
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	59.40	59.40
1	SENSOR PRIMED (SN)	SERVICEABLE	172.33	-
1	SEAL RING SATIN BLACK (SN)	NOT NECESSARY	1.21	-
1	SUPPORT PART BUMPER INNER BRACKET LH (SN)	CRACKED	54.69	54.69
1	GUIDE PIECE BUMPER SIDE BRACKET LH (SN)	CRACKED	20.91	20.91
1	GUIDE PIECE BUMPER SIDE BRACKET RH (SN)	NOT NECESSARY	20.91	-
1	COVER PART FOR BUMPER SAT LHS FOG LAMP GRILLE (SN)	DEFORMED	27.86	27.86
1	COOLING AIR GRILL SATIN B LHS FOG LAMP GRILLE LOWER TRIM (SN)	SERVICEABLE	91.45	-
2	CLAMP CLIP (SN)	NECESSARY	5.60	5.60
1	HEADLAMPS FOR CURVE LIGHT LH (SN)	CRACKED	2,091.76	2,091.76
1	BALLAST FOR GAS DISCHARGE (SN)	SERVICEABLE	791.96	-
1	POWER MODULE FOR DAY DRIV (SN)	SHORTED	392.42	392.42
1	POWER MODULE FOR CORNERIN (SN)	SERVICEABLE	507.12	-
1	FLAT CONTACT HOUSING WITH H/LAMP WIRE HOUSING (SN)	CRACKED	18.43	18.43
1	WASH WATER RESERVOIR (SN)	DEFORMED	135.38	135.38
1	SEAL RING (SN)	NECESSARY	9.86	9.86
1	WATER LEVEL SWITCH (SN)	NECESSARY	27.69	27.69
1	SEALING CAP (SN)	NECESSARY	12.65	12.65
1	GASKET (SN)	NECESSARY	1.95	1.95
1	GASKET (SN)	NECESSARY	4.70	4.70
1	WINDSHIELD CLEANER CONCEN (SN)	NECESSARY	15.71	15.71
1	COUPLING PIECE (SN)	NECESSARY	17.66	17.66

Report Ref No. CC4/FCI20014050/R1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COUPLING PIECE (SN)	NECESSARY	17.66	17.66
1	FENDER FENDER LH (SN)	BENT	615.49	615.49
1	CROSS MEMBER FENDER BRACKET LH (SN)	BENT	31.68	31.68
4	RIVETTED CAP NUT (SN)	NECESSARY	8.92	8.92
1	WHEELHOUSE LINER LHS FENDER LINER (LOWER) (SN)	SERVICEABLE	84.97	-
1	WHEELHOUSE LINER LHS FENDER LINER (UPPER) (SN)	CRACKED	181.47	181.47
1	SOUND ABSORBER FOR FENDER LHS FENDER ELEMENT (SN)	DEFORMED	47.36	47.36
1	SOUND ABSORBER FOR FENDER LHS FENDER INNER TOP SPONGE (SN)	SERVICEABLE	15.07	-
1	SECTIONAL PART-PILLAR A/B(SN)	BENT	1,010.92	1,010.92
2	RIVETTED CAP NUT (SN)	NECESSARY	4.46	4.46
2	BOLT HEX HD (SN)	NECESSARY	4.38	4.38
1	2K-FULLSCHAUM (SN)	NECESSARY	144.94	144.94
1	SEALANT CAN BE SPRAYED (SN)	NECESSARY	61.67	61.67
1	ZINC SPRAY (SN)	NECESSARY	62.88	62.88
1	2K-BODY ADHESIVE (SN)	NECESSARY	406.76	406.76
1	REAR VIEW MIRROR HOUSING LHS MIRROR HOUSING (SN)	SERVICEABLE	562.83	-
1	MIRROR CAP PRIMED (SN)	TO REPAIR SEE LABOUR	167.56	-
1	MIRROR GLASS (SN)	SERVICEABLE	180.70	-
1	DOOR LHS FRT DOOR (SN)	BENT	2,004.50	2,004.50
6	CLIP DOOR BOARD CLIP (SN)	NECESSARY	8.94	8.94
1	SOUND ABSORBER LAMINATED DOOR INSULATOR (SN)	NECESSARY	41.40	41.40
1	DOOR SEAL (SN)	NECESSARY	103.28	103.28
1	FELT STRIP (SN)	NECESSARY	19.82	19.82
1	DOOR HINGE LHF DOOR LOWER HINGE (SN)	SERVICEABLE	129.72	-
1	OVAL HEXAGON SOCKET HEAD (SN)	NECESSARY	2.76	2.76
2	ALLOY WHEEL GALVANO GREY (SN)	SCRATCHED	2,674.28	2,674.28
2	RUBBER VALVE (SN)	NECESSARY	6.58	6.58
1	PIRELLI CINTUP7 225/40R18 (SN)	SCRATCHED	680.00	476.00
1	NOZZLE CYLINDER LH (ADDITIONAL) (SN)	CRACKED	129.30	129.30
1	SET OF SHRINK FIT SLEEV (ADDITIONAL) (SN)	NECESSARY	64.39	64.39

Report Ref No. CC4/FCI20014050/R1ea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
			15,457.75	12,339.81
	<u>LABOUR</u>			
	TOWING ASSISTANCE -AWP .		195.00	195.00
	LABOUR .INCLUSIVE OF THE REPAIR OF MIRROR CAP PRIMED.		6,720.00	3,360.00
	SPRAY PAINT.		6,400.00	4,800.00
	TRANSFER DOOR MECHANISM .		840.00	420.00
	R&R FRT LUGGAGE TRIM .		840.00	420.00
	CHECK SHORT CIRCUIT/HARNESS REPAIR .		280.00	280.00
	DIAGNOSTIC AND PROGRAMMING .		480.00	480.00
	TO ALIGN LED HEADLIGHT .		100.00	100.00
	R&R RIM & BALANCE .		100.00	100.00
	WHEEL ALINGMENT .		360.00	360.00
			16,315.00	10,515.00
	GRAND TOTAL		31,772.75	22,854.81
RECOMMENDED COST OF REPAIRS				22,854.81

Report Ref No. CC4/FCI20014050/R1ea3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLG 6352R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLG 6352R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

