

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO20014051/QUvd3e2 Ref: 50 RAFFLES PLACE #03-03 SINGAPORE LAND 05/01/2021 Date: **TOWER SINGAPORE 048623** Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SKV 3058T** Veh. Inspected **GBA 111J** Policy No. D20MTPV01014958 Coverage (\$) 0.00 Claim No. CMTD2003576/GPL Excess (\$) 0.00 **Assign Date GRACE TEO** 17/12/2020 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE AUTO Make & Model 2982 C.C HIDDEN 2007 Engine No. Year of Reg. JTFHT02P200001758 WHITE Chassis No. Colour Odometer 500948 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15 LINAM 6 mm LINAM L/H Front Tyre 195 R15 6 mm 195 R15 LINAM R/H Rear Tyre 6 mm LINAM L/H Rear Tyre 195 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 04/12/2020 Inspect Date / Time 04/01/2021 (11:35 AM) Accident Date PAUL HOE BATTERIES & MOTOR SERVICES Survey held at BLK 1 KAKI BUKIT AVE 6 #01-109 AUTOBAY SINGAPORE 417833 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/SMO20014051/QUvd3e2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

SEON And a Committee of OAE I become a American

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser