# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Liu Chun Cheong Date: 25 Jun 2021

# **Preliminary Advice**

Insured Vehicle No : SFE3311K

TP Vehicle No : SHA9366K Accident Date : 01/12/2020

Make : HYUNDAI I40 Assignment Date : 18/01/2021

Date of Inspection : 18/12/2020 Est. Duration of Repair : 9

Inspection At : BIFROST AUTO PTE LTD (KAKI BUKIT)

8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT

SINGAPORE 415875

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,567.90
Revised Amount	:S\$	18,977.32
Check Items (Estimated)	:S\$	0.00
Total	:S\$	18,977.32
Lump Sum Repair	:S\$	15,000.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
)	Other comments :