

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI20014055/T1VD3Q2**Date:** 14/01/2021REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	ML000134
Claimant		
Vehicle No : SHD1469J	Insured Vehicle No :	SLF7003Y
Date of Loss: 16/12/2020	Nature of Claim:	TP
		Claim No: M2006226

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD1469J		
Make & Model:	HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No:	D4FBGZ127645
Reg. Date:	26/07/2017 (Man. Year: 2016)	Chassis No:	TMAD281UVHJ129432
Colour:	Silver	Odometer:	282842 km
Engine Capacity:	1582 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,618.87	1,348.89	3,269.98	70.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	780.00	620.00	44.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,018.87	2,128.89	3,889.98	64.63
Approved Total (Overridden) (S\$)		1,700.00		
	(S\$)	6,018.87	1,700.00	4,318.87
	+ GST 7.00/7.00% (S\$)	421.32	119.00	302.32
	Nett Amount (S\$)	6,440.19	1,819.00	4,621.19

INSPECTION

Date of Assignment: 17/12/2020

Date Inspected: 18/12/2020 Inspected At:

Premier Automotive Services Pte Ltd
(HQ)
23 Changi South Ave 2, #01-02
Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Jan 2021)	
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD1469J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*O/S MIRROR ASSY	Cut	742.49 FL	-	*742.49 FL
2	1		*SUPPORT PANEL	Not Necessary	1,243.60 FL	-	*- FL
3	1		*WASHER TANK	Not Necessary	51.40 FL	-	*- FL
4	1		*FRONT BUMPER O/S FOG LAMP COVER	Not Necessary	25.00 FL	-	*- FL
5	1		*FRONT N/S FOG LAMP	Not Necessary	840.90 FL	-	*- FL
6	1		*FRONT O/S CORNER BRACKET	Not Necessary	92.60 FL	-	*- FL
7	1		*FRONT O/S HEAD LAMP	Not Necessary	1,531.57 FL	-	*- FL
8	1		*FRONT BUMPER	Deformed	811.11 FL	-	*811.11 FL
9	1		*FRONT BUMPER EMBLEM	Not Necessary	27.80 FL	-	*- FL
10	1		*FRONT BUMPER O/S SIDE BRACKET	Necessary	32.51 FL	-	*32.51 FL
11	1		*FRONT BUMPER O/S UPPER BRACKET	Not Necessary	92.60 FL	-	*- FL
12	1		*FRONT BUMPER O/S SUPPORT BRACKET	Not Necessary	37.01 FL	-	*- FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	-	*30.00 FS
14	1		*FRONT NO PLATE WITH CASING	Not Necessary	40.00 FS	-	*- FS
15	1		*FRONT O/S FENDER STICKER	Necessary	30.00 FS	-	*30.00 FS
16	1		*SET FRONT O/S FENDER INNER SHIELD CLIPS	Not Necessary	28.00 FS	-	*- FS
17	1		*SUNDRY	Necessary	50.00 FS	-	*20.00 FS

F=Franchise part. S=SpcNett. L=LisItemDisc.

Sub Total (\$\$)	5,724.59	1,666.11
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,105.72	317.22
Total Parts (\$\$)	4,618.87	1,348.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	80.00	80.00
2	TO FOCUS/CHECK FRONT N/S & O/S HEAD LAMPS	New	60.00	0.00
3	TO DISMANTLE/REFIT THE INNER GARNISHES,INNER LININGS,INNER TRIMS,CUSHION SEAT,CARPET,ETC TO FACILITATE REPAIRS	New	180.00	0.00
4	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK-OUT,STRAIGHTEN,REPAIR,RESHAPE AND ADJUST OF THE SAME	New	600.00	300.00
5	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER,FRONT O/S FENDER	New	400.00	400.00
6	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	80.00	0.00
Gross Labour Cost (\$\$)			1,400.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >