

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20014063/QGA3Q2

**Date:** 13/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900086399

**Claimant Vehicle No :** SHD6272B **Insured Vehicle No :** SMK8336S

Date of Loss: 09/12/2020 Nature of Claim: TP Claim No: 4030134613SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD6272B</b>		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZR1681249
Reg. Date:	24/06/2016 (Man. Year: 2015)	Chassis No:	JTDKN36U905768181
Colour:	Maroon	Odometer:	633089 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,869.00	981.72	4,887.28	83.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,103.00	440.00	1,663.00	79.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$)</b>	<b>7,972.00</b>	<b>1,421.72</b>	<b>6,550.28</b>	<b>82.17</b>
<b>Approved Total (Overridden) (\$)</b>		<b>1,250.00</b>		
<b>Nett Amount (\$)</b>	<b>7,972.00</b>	<b>1,250.00</b>	<b>6,722.00</b>	<b>84.32</b>
<b>+ Loss of Use (4.5 x \$50.00/day) (\$)</b>		225.00		
<b>+ Car Rental (4.5 x \$108.61/day) (\$)</b>		488.75		
<b>+ Doc/Search Fee (\$)</b>		7.00		
<b>Nett Liability (\$)</b>		<b>1,970.75</b>		

### INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 2.0 days

**Adjuster:** OI SUN PIN**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	12.10 F	*15.75 F
2	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
3	1		*TAIL LAMP RH (DISC 10%)	Cracked	557.80 F	*502.02 F
4	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
5	1		*SEALANT W/SCREEN	Serviceable	37.00 F	*- F
6	1		*TAIL LAMP RH	Serviceable	557.80 F	*- F
7	1		*SPOILER REAR	Serviceable	953.70 F	*- F
8	1		*TAILGATE ASY	Serviceable	1,007.90 F	*- F
9	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
10	1		*UNDER COVER SUB-ASSY ,RR FLOOR	Serviceable	514.50 F	*- F
11	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
12	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
13	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
14	1		*BUMPER SEAL ,RR RH	Serviceable	65.70 F	*- F
15	1		*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
16	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
17	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
18	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
19	1		*ANTENNA ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
20	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
21	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
22	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F

F=Franchise part.

**Total Parts (\$\$)**      **5,869.00**      **981.72**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	507.00	200.00
2	SPRAY PAINT	New	1,116.00	200.00
3	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	0.00
4	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
5	TO REPLACE SUNDRY PARTS	New	100.00	0.00
6	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
7	TO WASH AND VACUUM	New	60.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,103.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >