

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20014066/GVD3E2

Date: 24/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SDD180U

Insured Vehicle No : SKU5969G

Date of Loss: 09/12/2020

Nature of Claim: TP Claim No: 4533461286SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDD180U**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UJC3464

Reg. Date: 18/11/2019 (Man. Year: 2019)

Chassis No: MMBSTA13AKH003643

Colour: Grey

Odometer: 68318 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020 Inspected At:

1st Auto Pro Pte Ltd - 8 Kaki Bukit (HQ)
8 Kaki Bukit Avenue 4, #01-51/52 PREMIER @ KAKI
BUKIT
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Repair	0.00 F	*- F
2	1		*FRT BUMPER	Deformed	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER LOWER SPOILER	Cracked	0.00 F	*- F
5	1		*FRT LH HEADLAMP ASSY	Scratched	0.00 F	*- F
6	1		*FRT LH FENDER	Buckled	0.00 F	*- F
7	1		*FRT LH FENDER EMBLEM	Necessary	0.00 F	*- F
8	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
9	1		*FRT LH SHOCK ABSORBER	* Check	0.00 F	*- F
10	1		*FRT LH KNUCKLE ARM	* Check	0.00 F	*- F
11	1		*FRT LH KNUCKLE ARM BEARING	* Check	0.00 F	*- F
12	1		*REAR LH DOOR	Repair	0.00 F	*- F
13	1		*FRONT LH FOG LAMP	Cracked	0.00 F	*- F
14	1		*FRONT LH FOG LAMP GARNISH	Broken	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
-------------------	------	------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >