

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20014070/UVD3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : GBA5560M

Insured Vehicle No : YN6740M

Date of Loss: 09/12/2020

Nature of Claim: TP

Claim No: CDMCG20001865

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBA5560M**

Make & Model: TOYOTA DYNA, 3.0 D (M)

Engine No: 1KD1663827

Reg. Date: 20/08/2007 (Man. Year: 2007)

Chassis No: JTFAT35Y503001209

Colour: Red

Odometer: 529102 km

Engine Capacity: 2982 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size:

155R12(D)

Front Left Side: Austone 6 mm

Rear Left Side:

Dunlop 6/6 mm

Front Right Side: Austone 6 mm

Rear Right Side:

Dunlop 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,819.95	1,551.82	3,268.13	67.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,360.00	1,400.00	50.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,579.95	2,911.82	4,668.13	61.59
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	7,579.95	2,300.00	5,279.95	69.66
+ GST 7.00/7.00% (S\$)	530.60	161.00	369.60	69.66
Nett Amount (S\$)	8,110.55	2,461.00	5,649.55	69.66

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020 Inspected At:

Liu's Brother Auto Workshop (HQ)

1 Kaki Bukit Ave 6 #01-01, Auto

Bay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Dec 2020)	
Parts:	N/A	TOYOTA DYNA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA5560M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	1,035.40 F	*1,035.40 FL
2	1		*FRONT GRILLE	Cracked	587.65 F	*424.20 FL
3	1		*SET FRONT GRILLE CLIP	Necessary	50.00 F	*50.00 FL
4	1		*FRONT DYNA EMBLEM	Necessary	71.00 F	*71.00 FL
5	1		*FRONT PANEL GARNISH	Cut	328.50 F	*328.50 FL
6	1		*FRONT AIRCON COOLING COIL UNIT	Not Necessary	628.00 F	*- FL
7	1		*FRONT AIRCON BLOWER	Not Necessary	1,919.40 F	*- FL
8	1		*FRONT CORPORATE ADVERTISEMENT & ARTWORK	Necessary	200.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,819.95	2,029.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	477.28
Total Parts (\$\$)	4,819.95	1,551.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	REMOVE & REINSTALL DASHBOARD,METER INSTRUMENTS,DISCONNECT WIRING & ETC	New	400.00	160.00
3	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00
4	TO REMOVE & REFIX AIR CON,RE-FILL AIR CON GAS & TEST FOR LEAKAGES	New	250.00	100.00
5	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS	New	900.00	600.00
6	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	1,080.00	450.00
Gross Labour Cost (\$\$)			2,760.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >