

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014075/UVF3E2

Date: 11/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00131392001
Claimant Vehicle No: JTY2960 Insured Vehicle No: SKC6669K
Date of Loss: 20/11/2020 Nature of Claim: TP Claim No: SNM20D204895/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: JTY2960
Make & Model: YAMAHA 135LC, 134cc ES Engine No: G3G5E173639
Reg. Date: 15/03/2020 (Man. Year: 2020) Chassis No: PMYUG0810L0173599
Colour: Red Odometer: 5682 km
Engine Capacity: 134 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70-90-17 Rear Tyre Size: 80-90-17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,236.80	2,606.10	1,630.70	38.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	285.00	595.00	67.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,116.80	2,891.10	2,225.70	43.50
Approved Total (Overridden) (\$\$)		2,100.00		
Nett Amount (\$\$)	5,116.80	2,100.00	3,016.80	58.96

INSPECTION

Date of Assignment: 20/12/2020
Date Inspected: 18/12/2020 Inspected At: Erofia Automotive Pte Ltd (HQ)
#02-62
SINGAPORE 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Jan 2021)	
Parts:	N/A	YAMAHA 135LC 134cc ES (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for JTY2960)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK TUBE ASSY	O/S Dented	640.00 FL	*280.00 FL
2	1		*FORK UNDER BRACKET	Bent	185.00 FL	*165.00 FL
3	1		*FRONT WHEEL RIM	Cut	380.00 FL	*380.00 FL
4	1		*FRONT RIM SHAFT	Cut	45.00 FL	*45.00 FL
5	1		*FRONT RIN BEARING	Necessary	38.00 FL	*38.00 FL
6	1		*HANDLE BAR	Bent	88.00 FL	*88.00 FL
7	1		*HANDLE BAR END	O/S Scratched	80.00 FL	*40.00 FL
8	1		*SET HAND GRIP	Torn	55.00 FL	*55.00 FL
9	1		*FRONT SIGNALS	O/S Scratched	140.00 FL	*70.00 FL
10	1		*SIDE MIRROR O/S	Cut	55.00 FL	*55.00 FL
11	1		*HEADLAMP	Scratched	185.00 FL	*185.00 FL
12	1		*WINDSHIELD	Scratched	55.00 FL	*55.00 FL
13	1		*HORN COVER INNER	Cut	80.00 FL	*80.00 FL
14	1		*LOWER SIDE COVER (MATT BLACK)	Cut	68.00 FL	*68.00 FL
15	1		*SET FAIRING ASSY	Cut	525.00 FL	*525.00 FL
16	1		*FRONT FOOTREST BRACKET	Serviceable	65.00 FL	*- FL
17	1		*FRONT FOOTREST RUBBERS	O/S Torn	70.00 FL	*35.00 FL
18	1		*BRAKE PEDAL	Not Necessary	42.00 FL	*- FL
19	1		*BRAKE MASTER PUMP	Cut	185.00 FL	*185.00 FL
20	1		*KICK STARTER	Cut	85.00 FL	*85.00 FL
21	1		*REAR FOOTRESTS	O/S Cut	80.00 FL	*40.00 FL
22	2		*REAR FOOTREST BRACKETS	Not Necessary	156.00 FL	*- FL
23	1		*EXHAUST ASSY	Serviceable	485.00 FL	*- FL
24	1		*EXHAUST PROTECTOR - CHROME	Cut	60.00 FL	*60.00 FL
25	1		*EXHAUST PROTECTOR - BLACK	Cut	45.00 FL	*45.00 FL
26	1		*BASKET	Cut	50.00 FL	*50.00 FL
27	1		*SET NUMBER PLATE	Necessary	28.00 FS	*10.00 FS
28	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
29	1		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
30	1		*SET STEERING CONE	Necessary	90.00 FS	*50.00 FS
31	1		*REAR BOX	Missing	200.00 FS	*180.00 FS
32	1		*REAR BOX BRACKET	Not Necessary	85.00 FS	*- FS
33	1		*E.R.P. IU	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,631.00	2,869.00
- List Item Discount on L Items 10.00/10.00% (S\$)	394.20	262.90
Total Parts (S\$)	4,236.80	2,606.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	400.00	250.00
4	TO REPAIR BODY FRAME	New	350.00	0.00
Gross Labour Cost (\$\$)			880.00	285.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >