

ASS. REC. BY: *marcus*

CS/ CY120014075/UNF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

RM \$6500

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIS / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

JT42960

3 / 20

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIS / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Sum insured RM \$6800

30/11/20 1/5 @ 2100 confirmed with insurer (Red 3016.80, 58%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 30/12/20-Typist

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format: Merimen

Lump Sum / L.B. (\$ 2100)

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

CHINA

Name : Wan Muhammad Isa Al-Bahri Bin Wan Setapa

Accident Date : 20-Nov-20

Vehicle No : JTY2960

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Qty	Description List Items	Amount S(\$)
2	Front fork tube assy 0/5 m 1 pc	\$ 640.00 320
1	Fork under bracket Bent	\$ 185.00
1	Front wheel rim cur	\$ 380.00
1	Front rim shaft cur	\$ 45.00
1	Front rim bearing new	\$ 38.00
1	Handle bar Bent	\$ 88.00
2	Handle bar end 0/5 sc 1 pc	\$ 80.00 40
1	Hand grip (1 set) Torn	\$ 55.00
2	Front signals 0/5 sc 1 pc	\$ 140.00 70
1	Side mirror 0/5 cur	\$ 55.00
1	Headlamp sc	\$ 185.00
1	Windshield sc	\$ 55.00
1	Horn cover inner cur	\$ 80.00
1	Lower side cover (matt black) cur	\$ 68.00
1	Fairing assy (1 set) cur	\$ 525.00
1	Front footrest bracket sul x	\$ 65.00 X
2	Front footrest rubbers 0/5 70.1 1 pc	\$ 70.00 35
1	Brake pedal 11 x	\$ 42.00 X
1	Brake master pump cur	\$ 185.00
1	Kick starter cur	\$ 85.00
2	Rear footrests 0/5 cur 1 pc	\$ 80.00 40
2	Rear footrest brackets 11 x	\$ 156.00 X
1	Exhaust assy sul x	\$ 485.00 X
1	Exhaust protector - chrome cur	\$ 60.00
1	Exhaust protector - black cur	\$ 45.00
1	Basket cur	\$ 50.00
		\$ 3,942.00
	Less 10%	\$ 394.20
		\$ 3,547.80

2629

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

Email: erofia@singnet.com.sg

Name : Wan Muhammad Isa Al-
Bahri Bin Wan Setapa

Accident Date : 20-Nov-20

Vehicle No : JTY2960

Vehicle Model : Yamaha 135LC

Estimated Repair Costs

Special Net Items

1	Number plste (1 set) <i>nee 10</i>	\$	28.00 <i>10</i>
2	Fork oils <i>11 X</i>	\$	30.00 <i>X</i>
2	Fork oil seals <i>11 X</i>	\$	56.00 <i>X</i>
1	Steering cone (1 set) <i>nee</i>	\$	90.00 <i>50</i>
1	Rear box <i>mis 150</i>	\$	200.00 <i>150</i>
1	Rear box bracket <i>11 X</i>	\$	85.00 <i>X</i>
1	E.R.P. IU <i>11 X</i>	\$	200.00 <i>X</i>
		\$	<u>689.00</u>

S/No. Labour

1	To provide towing service	<i>35</i>	\$	50.00
2	To check wiring and reset headlamp focusing	<i>11 X</i>	\$	80.00
3	To provide labour	<i>250</i>	\$	400.00
4	To repair body frame	<i>11 X</i>	\$	350.00
			\$	<u>880.00</u>

Grand Total

\$ 5,116.80

Dollars: Five Thousand One Hundred Sixteen and Cents: Eighty only

2891.1

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: