Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20014076/UTF3Q2

**Date:** 30/12/2020

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001317846

Claimant GBC8824Y Insured Vehicle No: GBG2889D

Vehicle No:

Date of Loss: 15/12/2020 Nature of Claim: TP Claim No: 251069

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBC8824Y

 Make & Model:
 FIAT DOBLO, 1.6 D CARGO MJ (M)
 Engine No:
 198A30007001807

 Reg. Date:
 17/02/2014 (Man. Year: 2013)
 Chassis No:
 ZFA26300006106213

Colour: White Odometer: 158436 km

Engine Capacity: 1598 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/60R16 Rear Tyre Size: 195/60R16
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,146.30	2,542.74	6,603.56	72.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,210.00	550.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,906.30	3,752.74	7,153.56	65.59
Approved Total (Overridden) (S\$)		3,000.00		
(S\$)	10,906.30	3,000.00	7,906.30	72.49
+ GST 7.00/7.00% (S\$)	763.44	210.00	553.44	72.49
Nett Amount (S\$)	11,669.74	3,210.00	8,459.74	72.49

**INSPECTION** 

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020 Inspected At: Liu's Brother Auto Engineering

Workshop (HQ)

BLK 1 KAKI BÚKIT AVE 6, #01-01

AUTO BAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: DENISE TAY KWEE CHENG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

#### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 30 Dec 2020)

Parts: N/A FIAT DOBLO 1.6 D CARGO MJ (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBC8824Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,245.50 F	*864.07 FL
2	1		*SET FRONT BUMPER CLIPS	Necessary	68.00 F	*50.00 FL
3	1		*FRONT BUMPER SPONGE	Serviceable	117.60 F	*- FL
4	1		*FRONT BUMPER BRACKET LH	Cracked	171.80 F	*65.00 FL
5	1		*FRONT HEADLAMP ASSEMBLY	N/s Cracked	1,317.40 F	*658.70 FL
6	1		*FRONT LH HEADLAMP LOWER PANEL	Bent	370.00 F	*370.00 FL
7	1		*FRONT LH FENDER	Buckled	780.00 F	*645.00 FL
8	1		*FRONT LH FENDER COWLING	Torn	466.00 F	*122.50 FL
9	1		*SET FRONT LH FENDER COWLING CLIPS	Necessary	60.00 F	*50.00 FL
10	1		*FRONT LH WIPER TANK	Serviceable	280.00 F	*-FL
11	1		*FRONT LH ABS MASTER PUMP	Not Necessary	4,270.00 F	*-FL
F=Fra	anchise	part. L=ListIt	emDisc.			
				Sub Total (S\$)	9,146.30	2,825.27
			- List Item Discount on L Items	0.00/10.00% (S\$)	0.00	282.53
				Total Parts (S\$)	9,146.30	2,542.74
				` '-		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	80.00	20.00				
2	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS	New	800.00	560.00				
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA	New	800.00	600.00				
4	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00				
	Gross Labour Cost (S\$)		1,760.00	1,210.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.