

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Anniated to redefation internationale des Experts En Automobile						
	AIG ASIA PACIFIC	INSURANCE PTE LTD		Ref:	CS3/AIG20007671/Gqf3e2-1	
	78 SHENTON WAY AIG BUILDING SINGAPORE 0791			Date:	04/03/2021	
	ATTN : CHEOK LE	E WAI		Code:	AIG	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SLG 4749T	Veh. Inspected		FU 396B	
	Policy No.	2100484521	Coverage (\$)		0.00	
	Claim No.	1881466184SG	Excess (\$)		0.00	
	Assign From	CHEOK LEE WAI	Assign Date		18/12/2020	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA AEROX GDR155A	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	MH3SG4640KJ050351	Colour		BLACK	
	Odometer	10642 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	90/90-14	MAXXIS		5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	100/90-14	MAXXIS		5 mm	
	L/H Rear Tyre				mm	
4.	. Description of Damages					
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.					
	REPAIR CONDITION SEE DETAILS.					
5.	General Information					
	Accident Date	22/07/2020	Inspection Date	е	11/02/2021	
	Survey held at	LKT GROUP PTE LTD				
		3006 UBI ROAD 1 #01-384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					