

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

FRE-REFAIR INSPECTION REFORT						
	MS FIRST CAPITA	L INSURANCE LTD	F	Ref:	CS3/FCI20014092/Qqd3e2	
	36 ROBINSON RO SINGAPORE 0688	AD #16-01 CITY HOUSE 77	]	Date:	28/12/2020	
			(	Code:	FCI2	
1.	1. Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 8099C	Veh. Inspected		SKU 7497M	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D20005123MFSH	Excess (\$)		0.00	
	Assign From	SANGHILAN VIC	Assign Date		18/12/2020	
2. Vehicle Particulars & Condition						
	Make & Model	B.M.W. 116D	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	WBA1V720205C06824	Colour		BLACK	
	Odometer	58400 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	PIRELLI		6 mm	
	L/H Front Tyre	205/55 R16	PIRELLI		6 mm	
	R/H Rear Tyre	205/55 R16	PIRELLI		6 mm	
	L/H Rear Tyre	205/55 R16	PIRELLI		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5.	General Information					
	Accident Date	12/12/2020	Inspect Date / T	ime	18/12/2020 ( 04:40 PM )	
	Survey held at	ey held at KUM CHEW MOTOR WORKSHOP				
	160 SIN MING DRIVE #05-08 SIN MING AUTOCITY SINGAPORE 575722					
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$53,000.00					

Report Ref No. CS3/FCI20014092/Qqd3e2

Inspected By

OI SUN PIN

K.K.LAU CPT(RET)

Asst. Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser