

Your Ref: MSIG.20.0314.WT.mg

Date: 09<sup>th</sup> Feb 2021

Our Ref: CS1/LAW20014095/Ktd3e2

**M/s Msig Insurance (Singapore) Pte Ltd**

C/o : Willy Tay's Chambers

70 Shenton Way #17-02 Eon Shenton

Singapore 068807

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SFA 833L****INSURED VEHICLE: SMG 487M****ACCIDENT DATE: 09/03/2020**

We thank you for your instruction on 16/12/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SFA 833L from M/s KM Auto Assessors Pte. Ltd..
- b) Final Repair Bill of SFA 833L from M/s Choon Hock Motor Trading Co.
- c) Singapore Accident Statement of Vehicles SFA 833L and SMG 487M.
- d) Colour damaged vehicle photographs of SFA 833L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

## 1. Information Recorded: -

|                      |                        |
|----------------------|------------------------|
| Registration Number  | : SFA 833L             |
| Make & Model         | : Honda HRV 1.5 DX CVT |
| Chassis Number       | : JHMRU1810GX200370    |
| Year of Registration | : 2016                 |
| Engine Capacity      | : 1496 cc              |

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.