

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20014097/QBS3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SJF3387P	Insured Vehicle No :	SHD3274R
Date of Loss:	10/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120197

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF3387P		
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Engine No:	L15A5154402
Reg. Date:	27/05/2008 (Man. Year: 2007)	Chassis No:	GJ11203715
Colour:	Silver	Odometer:	213522 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,635.12	3,873.16	761.96	16.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	2,000.00	330.00	14.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,965.12	5,873.16	1,091.96	15.68
Approved Total (Overridden) (S\$)		4,700.00		

Nett Amount (S\$)	6,965.12	4,700.00	2,265.12	32.52
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
Nett Liability (S\$)		5,060.00		
Global Sum Settlement (S\$)		5,000.00		

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020 Inspected At: Seng Hong Kee Co (HQ)
 393F WOODLANDS ROAD, (YEW TEE INDUSTRIAL ESTATE)
 Singapore 677976

Estimated Period of Repair: 6.0 days

Adjuster: OI SUN PIN**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Apr 2021)
Parts:	M1-MPV	HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF3387P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,382.50 FL	*1,382.50 FL
2	1		*TAILGATE LOCK	Jammed	109.40 FL	*109.40 FL
3	1		*TAILGATE FRAME WEATHERSTRIP	Crumpled	191.20 FL	*191.20 FL
4	1		*TAILGATE CENTRE GARNISH	Crumpled	451.30 FL	*451.30 FL
5	1		*TAILGATE TOP SPOILER	Crumpled	750.00 FL	*600.00 FL
6	2		*TAILGATE LAMPS	Serviceable	490.60 FL	*- FL
7	2		*REAR NUMBER PLATE LAMPS	Serviceable	65.60 FL	*- FL
8	1		*REAR BUMPER	Crumpled	1,078.50 FL	*1,078.50 FL
9	1		*REAR BUMPER BEAM	Serviceable	90.00 FL	*- FL
10	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	50.00 FL	*- FL
11	1		*REAR END PANEL	Dented	508.70 FL	*508.70 FL
12	1		*REAR END PANEL GARNISH	Crumpled	138.60 FL	*138.60 FL
13	1		*SET REVERSE SENSOR	Crumpled	235.00 FS	*150.00 FS
14	1		*SET REAR NUMBER PLATE	Dented	45.00 FS	*45.00 FS
15	1		*TUBE TAILGATE GLASS SEALANT	Necessary	30.00 FS	*30.00 FS
16	1		*SET TAILGATE GLASS MOULDING	Necessary	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,696.40	4,765.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,061.28	892.04
Total Parts (\$\$)	4,635.12	3,873.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIX TAILGATE GLASS	New	150.00	100.00
2	TO REMOVE ALL LISTED PARTS ,STRAIGHTEN ,RESHAPE AND REPOSITION SPARE TYRE PANEL AND REAR END FLOOR ,CUT AND WELD REAR END PANEL ,REFIX AND REALIGN SAME	New	1,000.00	1,000.00
3	TO SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	800.00
4	TO ANTI-RUST AFFECTED AREAS	New	80.00	40.00
5	TO RENEW TAILGATE ,REFIX TAILGATE LOCK ,LOCK MECHANISM AND TAILGATE ATTACHMENTS	New	100.00	60.00
Gross Labour Cost (S\$)			2,330.00	2,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >