

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20014101/ATD3E2

Date: 25/05/2021

REFERENCE

Insured/Claimant:	WONG CHIN WAH	Policy No:	1900179022		
Date of Loss:	14/12/2020	Nature of Claim:	OD	Claim No:	9845964490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFU5183R	Engine No:	CZD886423
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF3XL1013109
Reg. Date:	31/10/2019 (Man. Year: 2019)	Odometer:	19155 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,886.00	2,179.60	7,706.40	77.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,872.00	1,722.00	2,150.00	55.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,758.00	3,901.60	9,856.40	71.64
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	12,958.00	3,101.60	9,856.40	76.06
Nett Amount (S\$)	13,865.06	3,318.71	10,546.35	76.06

INSPECTION

Date of Assignment:	18/12/2020		
Date Inspected:	18/12/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	2,045.00 FS	*1,634.80 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	58.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - RH	Not Necessary	109.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	188.00 FS	*- FS
5	1		*FRONT SPOILER	Not Necessary	379.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	151.00 FS	*120.80 FS
7	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	38.00 FS	*- FS
8	1		*HEADLIGHT MOUNTING - RH	Not Necessary	117.00 FS	*- FS
9	2		*FRONT WHEEL COVER - LH / RH	N/S Necessary / O/S Cut	530.00 FS	*424.00 FS
10	1		*LED HEADLIGHT - RH	Not Necessary	5,526.00 FS	*- FS
11	1		*LIFT CYLINDER - RH	Not Necessary	208.00 FS	*- FS
12	1		*WHEEL HOUSING LINER - RH FRONT	Not Necessary	237.00 FS	*- FS
13	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	100.00 FS	*- FS
14	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 9,886.00 2,179.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
4	TO RESPRAY FRONT BUMPER	New	1,200.00	550.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,872.00	1,722.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >