Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20014108/R1PS3Q2

Date: 19/01/2021

REFERENCE

India International Insurance Pte Handling Insurer:

Ltd

Policy No: D20MFL0005826

Claimant Vehicle No:

SKZ8526E

No:

SMV9265Z

Odometer:

Date of Loss: 17/12/2020 Nature of Claim: TP Claim No:

79229 km

MFL2020D0002809

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ8526E

Make & Model: JAGUAR XE, 2.0 I4P TSS (A) Engine No: 015082054807204PT Reg. Date: 04/02/2016 (Man. Year: 2015) Chassis No: SAJAB4AG3GA905078

Insured Vehicle

Colour: Brown

Engine Capacity: 1999 cc Market Value/New Car

Price:

N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 225/50 R17 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,120.00	8,169.30	4,950.70	37.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	13,330.00	9,630.00	3,700.00	27.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,450.00	17,799.30	8,650.70	32.71
+ GST 7.00/7.00% (S\$)	1,851.50	1,245.95	605.55	32.71
Nett Amount (S\$)	28,301.50	19,045.25	9,256.25	32.71

Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020 Inspected At: Wearnes Automotive Pte Ltd (Leng

Kee 2)

45 Leng Kee Road Singapore 159103

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

MARKET VALUE: \$82,000.00

LTA REIMBURSEMENT VALUE (RV): \$67,948.00

NETT VALUE: \$14,052.00

Adjuster Report Page 4 of 5

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jan 2021)

Parts: 143 JAGUAR XE 2.0 I4P TSS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKZ8526E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Candition

Danairar'a

Amount

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No Oty Port No

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -BUMPER	Defaced	1,861.00 FS	*1,861.00 FS
2	1		*BRACKET -FEND RH	Cracked	37.10 FS	*37.10 FS
3	1		*BRACKET -FEND LH	*Check	37.10 FS	*-FS
4	1		*GRILLE -RADIA	Serviceable	473.50 FS	*-FS
5	1		*INSERT -FOAM	*Check	57.50 FS	*-FS
6	1		*PANEL -NOSE	Serviceable	97.30 FS	*-FS
7	1		*INSERT RH	Serviceable	24.10 FS	*-FS
8	1		*INSERT LH	Serviceable	24.10 FS	*-FS
9	1		*COVER WASHER RH	*Check	42.70 FS	*-FS
10	1		*MESH -GRILLE RH	*Check	256.60 FS	*-FS
11	1		*DUCT -AIR RH	*Check	110.10 FS	*-FS
12	1		*BONNET PANEL XE	Repair	1,375.10 FS	*-FS
13	1		*MOUNTING -BRA	*Check	27.70 FS	*-FS
14	1		*LINER -WHEELARCH RHF	Torn	349.70 FS	*349.70 FS
15	1		*JET-POWERWASH RH	*Check	305.80 FS	*-FS
16	1		*HEADLAMP RH	Broken	3,641.80 FS	*3,641.80 FS
17	1		*CROSSMEMBER	Serviceable	728.00 FS	*-FS
18	1		*FRAME-SUPPOR	Bent	453.40 FS	*453.40 FS
19	1		*BRACKET RH	Serviceable	69.00 FS	*-FS
20	1		*REINFORCEMENT	Serviceable	366.90 FS	*-FS
21	1		*FINISHER -VEN	Necessary	215.30 FS	*215.30 FS
22	1		*WHEEL-ROAD -ALLOY	Scratched	901.40 FS	*901.40 FS
23	1		*ADHESIVE SEALER FL2	Necessary	709.60 FS	*709.60 FS
24	1		*BODY PANEL SEALANT X	Serviceable	955.20 FS	*-FS
	anahiaa	part. S=SpcNe	att .			

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REPLACE FRT BUMPER ,BONNET ,FRT RH FENDER ,HEADLAMP RH ,REPAIR FRT RH DOOR ,A PILLAR RH	New	5,400.00	3,600.00				
2	TO SPRAYPAINT ON FRT BUMPER ,BONNET ,FRT RH FENDER ,FRT RH DOOR ,ETC	New	4,800.00	3,600.00				
3	TO REPLACE FRT RH RIM	New	50.00	50.00				
4	WHEEL ALIGNMENT	New	280.00	280.00				
5	TO FOCUS HEADLAMP	New	175.00	175.00				
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	525.00	525.00				
7	TO REMOVE ,REPLACE FRT RH SUSPENSION PARTS	New	2,100.00	1,400.00				
	Gross Labour Cost (S\$)		13,330.00	9,630.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.