

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG20014110/AGTD3Q2**Date:** 25/01/2021REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001265461
<b>Claimant</b>		
<b>Vehicle No :</b> SLC4593X	<b>Insured Vehicle No :</b>	SMJ125S
Date of Loss: 17/12/2020	Nature of Claim:	TP
		Claim No: 251104

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLC4593X</b>		
Make & Model:	HONDA VEZEL, 1.5 1.5X CVT (A)	Engine No:	L15B4028579
Reg. Date:	16/05/2016 (Man. Year: 2015)	Chassis No:	RU11108577
Colour:	Black	Odometer:	71802 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Roadstone 6 mm	Rear Left Side:	Achilles 6 mm
Front Right Side:	Roadstone 6 mm	Rear Right Side:	Achilles 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,888.10	4,641.36	6,246.74	57.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,960.00	1,040.00	34.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,888.10</b>	<b>6,601.36</b>	<b>7,286.74</b>	<b>52.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,888.10</b>	<b>5,200.00</b>	<b>8,688.10</b>	<b>62.56</b>

INSPECTION

Date of Assignment:	21/12/2020	
Date Inspected:	18/12/2020 Inspected At:	Hiap Hong Motor Repair (HQ) 2 Kaki Bukit Avenue 2, #02-13 Kaki Bukit Autohub Singapore 417921

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
<b>Parts:</b> M1-SUV	HONDA VEZEL 1.5 1.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC4593X)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	762.20 F	*762.20 FL
2	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER SIDE HOLDER RH	Necessary	27.10 F	*27.10 FL
4	1		*FRONT BUMPER LOWER SPOILER	Cut	351.00 F	*351.00 FL
5	1		*HEADLAMP RH	Not Necessary	1,827.80 F	*- FL
6	1		*FRONT RH FENDER	Dented	585.40 F	*585.40 FL
7	1		*FRONT RH FENDER INNER SHIELD	Not Necessary	166.50 F	*- FL
8	1		*FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
9	1		*FRONT RH FENDER ARCH GARNISH	Cut	153.00 F	*153.00 FL
10	1		*FRONT RH FENDER ARCH GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
11	1		*FRONT RH WHEEL RIM	Cut	800.00 FS	*400.00 FS
12	1		*FRONT RH TYRE	Not Necessary	300.00 FS	*- FS
13	1		*FRONT RH LOWER ARM	Bent	392.30 F	*392.30 FL
14	1		*FRONT RH SHOCK ABSORBER	Not Necessary	389.60 F	*- FL
15	1		*FRONT RH KNUCKLE ARM	Not Necessary	390.70 F	*- FL
16	1		*FRONT RH WHEEL HUB C/W BEARING	Damaged	193.50 F	*193.50 FL
17	1		*FRONT RH DOOR	Dented	958.90 F	*958.90 FL
18	1		*FRONT RH DOOR LOCK	Not Necessary	278.20 F	*- FL
19	1		*FRONT RH DOOR WEATHERSTRIPE	Not Necessary	195.80 F	*- FL
20	1		*FRONT RH DOOR BLACK TAPE	Necessary	50.00 FS	*50.00 FS
21	1		*REAR RH DOOR	Dented	966.50 F	*966.50 FL
22	1		*REAR RH DOOR LOCK	Not Necessary	270.20 F	*- FL
23	1		*REAR RH DOOR WEATHERSTRIPE	Not Necessary	187.60 F	*- FL
24	1		*REAR RH DOOR BLACK TAPE	Necessary	50.00 FS	*50.00 FS
25	1		*REAR RH FENDER ARCH GARNISH	Cut	195.00 F	*195.00 FL
26	1		*REAR RH FENDER ARCH GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
27	1		*REAR RH WHEEL RIM	Not Necessary	800.00 F	*- FL
28	1		*ROCKER PANEL OUTER SKIRTING	Cut	466.80 F	*466.80 FL
29	1		*ROCKER PANEL OUTER SKIRTING CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,888.10</b>	<b>5,651.70</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	0.00	1,010.34
<b>Total Parts (\$\$)</b>	<b>10,888.10</b>	<b>4,641.36</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	1,000.00	700.00
2	SPRAY PAINTING	New	1,000.00	800.00
3	WIRING	New	50.00	30.00
4	TO UNDERSEAL	New	150.00	40.00
5	TO TRANSFER FRONT AND REAR DOOR FITTINGS	New	300.00	160.00
6	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
7	TO DISMANTLE FRONT UNDERCARRIAGE	New	350.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,000.00</b>	<b>1,960.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >