

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20014113/UGS3Q2
Date: 08/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800049813
Claimant Vehicle No :	SMW7843M	Insured Vehicle No :	SLZ8405J
Date of Loss:	17/12/2020	Nature of Claim:	TP
		Claim No:	8290836521SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW7843M		
Make & Model:	MERCEDES-BENZ GLC300 SPORT, 2.0 4MATIC M-HYBRID (A)	Engine No:	26492030220093
Reg. Date:	10/12/2020 (Man. Year: 2019)	Chassis No:	WDC2539842F739090
Colour:	Grey	Odometer:	800 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,648.62	1,789.76	1,858.86	50.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	730.00	1,190.00	61.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,568.62	2,519.76	3,048.86	54.75
+ GST 7.00/7.00% (S\$)	389.80	176.38	213.42	54.75

Nett Amount (S\$)	5,958.42	2,696.14	3,262.28	54.75
+ Loss of Use (3.0 x S\$80.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,938.14		

INSPECTION

Date of Assignment: 31/12/2020

Date Inspected: 31/12/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Specialists Motor Pte Ltd (HQ)
Blk 3018A Ubi Road 1, #01-24/25/26
Singapore 408711

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Dented / Deformed	1,352.12 F	*1,352.12 FL
2	1		*REAR BUMPER PAD (CENTRE)	Grazed	566.50 F	*566.50 FL
3	1		*REAR BUMPER PAD (SIDE)	Not Necessary	59.00 F	*- FL
4	1		*REAR BUMPER DIFFUSER	Not Necessary	200.00 F	*- FL
5	2		*REAR BUMPER CHROME L&RH	Not Necessary	340.00 F	*- FL
6	1		*REAR BUMPER CHROME (CENTRE)	Not Necessary	149.00 F	*- FL
7	2		*REAR BUMPER SENSOR	Not Necessary	272.00 F	*- FL
8	1		*REAR BUMPER BEAM	Not Necessary	160.00 F	*- FL
9	2		*REAR FENDER ARCH GARNISH L&RH	Not Necessary	460.00 F	*- FL
10	1		*SET REAR BUMPER RIVET	Necessary	90.00 F	*70.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,648.62	1,988.62
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	198.86
Total Parts (S\$)	3,648.62	1,789.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW PARTS ,KNOCKING & WELDING REAR END PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS & RE-ALIGN BODY	New	780.00	300.00
2	REMOVE & REFIX REAR BUMPER SENSOR	New	100.00	50.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	680.00	300.00
4	DIAGNOSTIC & RESET	New	300.00	80.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	60.00	0.00
Gross Labour Cost (S\$)			1,920.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >