

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20014115/KES3Q2
Date: 20/12/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0002046_01
Claimant Vehicle No :	SMU8067R	Insured Vehicle No :	GBF2318R
Date of Loss:	16/12/2020	Nature of Claim:	TP
		Claim No:	MCV2021D0000374

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU8067R	Engine No:	33545990B38A15A
Make & Model:	BMW 218I, 1.5 COUPE LED NAV SR (A)	Chassis No:	WBA12AK0607F88981
Reg. Date:	28/08/2020 (Man. Year: 2020)	Odometer:	2613 km
Colour:	Metallic Blue		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 9 mm	Rear Left Side:	Bridgestone 9 mm
Front Right Side:	Bridgestone 9 mm	Rear Right Side:	Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,064.55	2,178.97	8,885.58	80.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,210.00	1,020.00	2,190.00	68.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,274.55	3,198.97	11,075.58	77.59
Approved Total (Overridden) (S\$)		2,550.00		

(S\$)	14,274.55	2,550.00	11,724.55	82.14
+ GST 7.00/7.00% (S\$)	999.22	178.50	820.72	82.14
Nett Amount (S\$)	15,273.77	2,728.50	12,545.27	82.14
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
Nett Liability (S\$)		3,328.50		

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020

Inspected At:

Yee Auto Pte Ltd (HQ)
 160 SIN MING DRIVE, #02-17 SIN MING AUTOCITY
 Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Nov 2021)
Parts:	M1-COUPE	BMW 218I 1.5 COUPE LED NAV SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU8067R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUZZER SENSOR	Serviceable	380.15 F	*- FL
2	1		*HANDBRAKE ECU	Serviceable	450.15 F	*- FL
3	1		*REAR BOOT LID	Repair	2,206.10 F	*- FL
4	1		*REAR BOOT LID 218I EMBLEM	Not Necessary	105.10 F	*- FL
5	1		*REAR BOOT LID LOCK	Repair	455.90 F	*- FL
6	1		*REAR BOOT LID LOGO EMBLEM	Dented	189.75 F	*82.10 FL
7	1		*REAR BOOT LID REFLECTOR	Serviceable	789.15 F	*- FL
8	1		*REAR BOOT LID WEATHERSTRIP	Serviceable	235.90 F	*- FL
9	1		*REAR BUMPER	Dented	1,810.20 F	*1,628.20 FL
10	1		*REAR BUMPER BRACKET-LH	Repair	132.20 F	*- FL
11	1		*REAR BUMPER BRACKET-RH	Repair	132.20 F	*- FL
12	1		*REAR BUMPER INNER IMPACT GARNISH	Cracked	198.20 F	*198.20 FL
13	1		*REAR BUMPER LOWER SPOILER	Mtg Cracked	385.15 F	*385.15 FL
14	1		*REAR BUMPER REFLECTOR -LH	Serviceable	128.50 F	*- FL
15	1		*REAR BUMPER REFLECTOR -RH	Serviceable	128.50 F	*- FL
16	1		*REAR BUMPER REINFORCEMENT	Repair	740.10 F	*- FL
17	1		*REAR BUMPER SIDE BRACKET -LH	Repair	320.00 F	*- FL
18	1		*REAR BUMPER SIDE BRACKET -RH	Repair	320.00 F	*- FL
19	1		*REAR BUMPER SPONGE	Serviceable	281.10 F	*- FL
20	1		*REAR BUMPER TOWING COVER	Serviceable	85.50 F	*- FL
21	1		*REAR END PANEL	Repair	420.15 F	*- FL
22	1		*REAR END PANEL TOP GARNISH	Serviceable	380.15 F	*- FL
23	1		*REVERSE SENSOR CENTRE -LH	Serviceable	395.20 FS	*- FS
24	1		*REVERSE SENSOR CENTRE -RH	Serviceable	395.20 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,064.55	2,293.65
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	114.68

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	11,064.55
						2,178.97

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS PANEL BEAT WHERE NECESSARY	New	1,200.00	400.00
2	TO PUTTY ,APPLY PRIMER & SPRAY -PAINT ON THE AFFECTED PORTION	New	1,200.00	600.00
3	TO APPLY RUST-PROOFING ON REPAIRED ,REPLACED PANEL	New	120.00	0.00
4	TO REMOVE/RENEW EXHAUST MUFFLER	New	250.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	80.00	20.00
6	TO REMOVE/TRANSFER TAILGATE COMPONENTS	New	80.00	0.00
7	COMPUTER DIAGNOSTIC RESET	New	280.00	0.00
Gross Labour Cost (S\$)			3,210.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >