



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SMB 8005U

| Qty | Description of Parts | Condition | Recommended (\$) |
|-----|------------------------------------|-----------|------------------|
| | <u>REPLACEMENT OF PARTS</u> | | |
| 1 | LETTER M CHROME, FRONT FACE LIFT | NECESSARY | 29.00 |
| 1 | LETTER A CHROME, FRONT FACELIFT | NECESSARY | 25.00 |
| 1 | LETTER N CHROME, FRONT FACELIFT | NECESSARY | 25.00 |
| 1 | STKR SBS TRANSIT FRT, SG BUS | NECESSARY | 1.00 |
| 1 | WIPER ARM.PANORAMIC.M431065 | SCRATCHED | 99.00 |
| 1 | HEADLAMP N/S | CRUSHED | 350.00 |
| 2 | HIGE N/S COMPARTMENT (F-06) | BENT | 64.00 |
| 1 | BRACKET N/S FRT BUMPER | BENT | 45.00 |
| 1 | COVER. FRP HEADLAMP N/S FRONT FRP | CRUSHED | 339.00 |
| 1 | SERVICE HATCH FRP FRONT. FRONT FRP | CRUSHED | 650.00 |
| 1 | BEARING ENT DOOR BRACKET | JAMMED | 55.00 |
| 1 | BUMPER CENTER FRONT. FRONT FRP | CRUSHED | 650.00 |
| 1 | HEADLAMP AUXILIARY W/FLASHER LH | CRUSHED | 199.00 |
| | | | 2,531.00 |
| | <u>LABOUR</u> | | |
| | WORKSHOP LABOUR. | | 192.00 |
| | CONTRACTOR'S REPAIR CHARGES. | | 1,950.00 |
| | | | 2,142.00 |
| | GRAND TOTAL | | 4,673.00 |

| | |
|------------------------------------|-----------------|
| RECOMMENDED COST OF REPAIRS | 4,673.00 |
|------------------------------------|-----------------|

Report Ref No. CS3/AIG20007822/Qpa3s2-1

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.