



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: JOANNE YONG		Ref: CS3/AIG20007822/Qpa3s2-1 Date: 30/12/2020 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SMG 6540C	Veh. Inspected	SMB 8005U
Policy No.	1900010125	Coverage (\$)	0.00
Claim No.	3794053682SG	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	18/12/2020
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MAN NG 363F	c.c	10518
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WMAA24ZZ2E7002230	Colour	GREEN
Odometer	297048 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Front Tyre	275/70 R22.5	FIRENZA	6 mm
R/H Rear Tyre	275/70 R22.5	FIRENZA	6 mm
L/H Rear Tyre	275/70 R22.5	FIRENZA	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	25/07/2020	Inspection Date	29/07/2020
Survey held at	3 Yio Chu Kang Crescent Singapore 786010		
Repairer	SBS TRANSIT LTD		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	