

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014147/T1PA3Q2
Date: 05/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1800085278	
Claimant Vehicle No : FBH8995K	Insured Vehicle No : SFF99M	
Date of Loss: 10/12/2020	Nature of Claim: TP	Claim No: 8605607445SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBH8995K		
Make & Model: YAMAHA FZ16, 153cc (M)	Engine No: 21CG023950	
Reg. Date: 04/11/2013 (Man. Year: 2013)	Chassis No: ME121C0G8D2023963	
Colour: Black	Odometer: 0 km	
Engine Capacity: 153 cc		
Market Value/New Car Price: N/A		
Sum Insured (\$\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80 R17	Rear Tyre Size: 140/60 R17	
Front Left Side: Pirelli 5 mm	Rear Left Side: Pirelli 5 mm	
Front Right Side: 0 mm	Rear Right Side: 0 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,872.00	2,449.80	422.20	14.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	630.00	410.00	220.00	34.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,502.00	2,859.80	642.20	18.34
Approved Total (Overridden) (\$\$)		2,300.00		
Nett Amount (\$\$)	3,502.00	2,300.00	1,202.00	34.32
+ Loss of Use (5.0 x S\$25.00/day) (\$\$)		125.00		
	Nett Liability (\$\$)	2,425.00		

INSPECTION

Date of Assignment: 21/12/2020		
Date Inspected: 21/12/2020	Inspected At:	Pang Scooter Service (HQ) BLK 1006 BUKIT MERAH LANE 2 #01-06 Singapore 159762
Estimated Period of Repair: 5.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

4/5/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER	Deformed	85.00 F	*85.00 FL
2	1		*SWING ARM	Bent	380.00 F	*380.00 FL
3	1		*REAR WHEEL	Bent	430.00 F	*430.00 FL
4	1		*SWING ARM BUSHING	Necessary	180.00 F	*180.00 FL
5	1		*SWING ARM SHAFT	Bent	65.00 F	*65.00 FL
6	1		*TAIL LIGHT ASSY	Cracked	65.00 F	*65.00 FL
7	1		*(NUMBER) PANEL	Cracked	15.00 F	*15.00 FL
8	1		*SIGNAL PLATE	Deformed	38.00 F	*38.00 FL
9	1		*HANDLER BAR	Not Necessary	65.00 F	*- FL
10	1		*CLUTCH LEVER	Cut	38.00 F	*38.00 FL
11	1		*L/H SIGNAL (FRONT)	Cut	38.00 F	*38.00 FL
12	1		*L/H MIRROR	Cut	38.00 F	*38.00 FL
13	1		*METER ASSY	Cut	250.00 F	*250.00 FL
14	1		*FRT HEADLAMP	Cut	360.00 F	*360.00 FL
15	1		*SIDE STAND	Bent	40.00 F	*40.00 FL
16	1		*HEAD LIGHT BRACKET	Dented	65.00 F	*65.00 FL
17	1		*REAR BOX	Dented	395.00 F	*395.00 FL
18	1		*BOX BRACKET	Not Necessary	85.00 F	*- FL
19	1		*L/H SIDE COVER	Cracked	45.00 F	*45.00 FL
20	1		*HANDLE CAP	Cut	30.00 F	*30.00 FL
21	1		*IU UNIT	Cut	165.00 F	*165.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,872.00	2,722.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	272.20
Total Parts (\$\$)	2,872.00	2,449.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PRESS REAR BODY FRAME	New	200.00	100.00
2	LABOUR	New	350.00	250.00
3	TRANSPORT	New	80.00	60.00
Gross Labour Cost (\$\$)			630.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >