

ASS. REC. BY:

REF:

CC4 / 119 2024147 / T. pa3.

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

94500

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Michael

Veh No:

FBH 8995K.

Yr Regn:

2013, Nov.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha FZ16.

C.C

153

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ME121 (098D) 20.2 3965.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

100/80 R17.

R:

140/60 R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

21/12/20

Survey held at

Pany Scooter

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.H. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp

(\$

☐

Interview

(\$

☐

Tech. Invs

(\$

☐

Weekend

(\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

ESTIMATE REPAIR

BIKE NO: FBH 8995K

DOA: 10/12/2020

MAKE/MODEL: YAMAHA FZ16

S/No	DESCRIPTION	AMOUNT	
1	REAR FENDER	\$ 85.00	del ✓
2	SWING ARM	\$ 380.00	bt ✓
3	REAR WHEEL	\$ 430.00	? ✓
4	SWING ARM BUSHING	\$ 180.00	rev ✓
5	SWING ARM SHAFT	\$ 65.00	? ✓
6	TAIL LIGHT ASSY	\$ 65.00	am ✓
7	(NUMBER) PLATE	\$ 15.00	cre ✓
8	SIGNAL PLATE	\$ 38.00	de ✓
9	TRANSPORT	\$ 80.00	60 ✓
10	HANDLER BAR	\$ 65.00	? ✓
11	CLUTCH LEVER	\$ 38.00	cut ✓
12	L/H SIGNAL (FRONT)	\$ 38.00	cut ✓
13	L/H MIRROR	\$ 38.00	cut ✓
14	METER ASSY	\$ 250.00	cut ✓
15	Frt headlamp	\$ 360.00	cut ✓
16	side stand	\$ 40.00	bt ✓
17	HEAD LIGHT BRACKET	\$ 65.00	del ✓
18	REAR BOX	\$ 395.00	del ✓
19	BOX BRACKET	\$ 85.00	? ✓
20	L/H SIDE COVER	\$ 45.00	cut ✓
21	HANDLE GRIP	\$ 30.00	cut ✓
22	PRESS REAR BODY FRAME	\$ 200.00	100 ✓
23	LABOUR	\$ 350.00	250 ✓
24	14 unit	\$ 165	cut ✓
25	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____		Tanpin 97445749 WP 21/12/20 1/5 Repair after repair. 5 days Tanpin @ Kuantan
26			
27			
28			
29			
30			
31			
32			
33			
34			
35			
36			
37			
Total:		\$ 3,337.00	