12/14/21, 12:22 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20014148/KGA3Q2

Date: 14/12/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900083505

Claimant Vehicle

No: SHD9942G Insured Vehicle No: SMK9803D

Date of Loss: 27/11/2020 Nature of Claim: TP Claim No: 2536590961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD9942G

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2H15357

Reg. Date: 06/11/2020 (Man. Year: 2020) Chassis No: TDKB3FUX03092621

Colour: Metallic Pearl White/Red Odometer: 6309 km

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm
Front Right Side: Dunlop 9 mm
Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,049.75	280.87	6,768.88	96.02
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,840.00	300.00	4,540.00	93.80
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	11,889.75	580.87	11,308.88	95.11
	+ GST 7.00/7.00% (S\$)	832.28	40.66	791.62	95.11
	Nett Amount (S\$)	12,722.03	621.53	12,100.50	95.11
	+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
	+ Car Rental (3.0 x	S\$81.13/day) (S\$)	243.39		
	+ Do	c/Search Fee (S\$)	7.45		
		Nett Liability (S\$)	1,022.37		
	Global Sui	m Settlement (S\$)	1,020.00		

INSPECTION

Date of Assignment: 30/11/2020

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

Date Inspected: 30/11/2020 Inspected At: 2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

1 12 112 113 113 113 113 113 113 113 113		*COVER ,REAR BUMPER *REINFORCEMENT SUB-ASSY ,REAR BUMPER *GUARD ,REAR BUMPER ,CENTER *RETAINER ,REAR BUMPER SIDE ,LH *RETAINER ,REAR BUMPER SIDE ,RH	Repair Serviceable Dented / Cut Serviceable	485.60 FL 332.70 FL 374.50 FL	*- Fl *- Fl
3 1 4 1 5 1 6 1 7 1 8 1		*GUARD ,REAR BUMPER ,CENTER *RETAINER ,REAR BUMPER SIDE ,LH	Dented / Cut		
1 5 1 6 1 7 1 8 1	 	*RETAINER ,REAR BUMPER SIDE ,LH		374.50 FL	
5 1 5 1 7 1 8 1	 		Serviceable		*374.50 Fl
5 1 7 1 8 1	<u> </u>	*DETAINED DEAD DIIMDED SIDE DU		132.60 FL	*- F
7 1 3 1		RETAINER, REAR BUNIFER SIDE, RE	Serviceable	132.60 FL	*- FI
3 1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- Fl
		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- Fl
) 1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- Fl
		*STAY ASSY, BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
0 1		*STAY ASSY, BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
1 1		*GLASS ,BACK WINDOW FIX	Serviceable	761.40 FL	*- FL
2 1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Serviceable	913.60 FL	*- FL
3 1		*ORNAMENT SUB-ASSY ,BACK DOOR	Serviceable	47.90 FL	*- FL
4 1		*PLATE ,LUGGAGE COMPARTMENT DOOR NAME ,NO,2	Serviceable	54.60 FL	*- FL
5 1		*PLATE ,BACK DOOR NAME ,NO.1	Serviceable	54.60 FL	*- FL
6 1		*LENS & BODY ,REAR COMBINATION LAMP ,NO.2 RH	Serviceable	261.00 FL	*- FL
7 1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Serviceable	339.60 FL	*- FL
8 1		*LENS & BODY ,REAR COMBINATION LAMP ,NO.2 LH	Serviceable	261.00 FL	*- FL
9 1		*LENS & BODY ,REAR COMBINATION LAMP ,LH	Serviceable	339.60 FL	*- FL
20 1		*COVER ,FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
21 1		*COVER ,FLOOR UNDER NO.1 (RH)	Serviceable	241.90 FL	*- FL
2 1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
23 1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
24 1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
25 1		*WHEELHOUSE LINER CLIP	Not Necessary	70.00 FS	*- FS
26 1		*BUMPER CENTRE GUARD CLIP	Not Necessary	80.00 FS	*- FS
7 1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
28 1		*REAR TAILGATE STICKER 6555-3333	Not Necessary 80.00 FS		*- FS
29 1		*REAR BUMPER PROTECTOR	Serviceable	180.00 FS	*- FS
30 1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS
31 1		*SET TAILLAMP CLIP	Not Necessary	50.00 FS	*- FS
32 1		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
3 1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
34 1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
		SpcNett. L=ListItemDisc.	riotriococcary	100.001 0	
	, 2 ,	•	Sub Total (S\$)	8,773.00	374.50
		- List Item Discount on L Items		1,723.25	93.63
			Total Parts (S\$)	7,049.75	280.87

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,600.00	80.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT TO FACILITATE BODYWORK REPAIR	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REMOVE AND REFIT REAR BIG & SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
	Gross Labour	4,840.00	300.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >