

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20014154/ABA3Q2
Date: 10/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100373455
Claimant Vehicle No :	SLZ2548U	Insured Vehicle No :	SFJ9180E
Date of Loss:	12/12/2020	Nature of Claim:	TP
		Claim No:	5317287931SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ2548U		
Make & Model:	BMW 116D, 1.5 D 5DR LED EU6 (A)	Engine No:	39355245B37D15A
Reg. Date:	27/04/2018 (Man. Year: 2018)	Chassis No:	WBA1V72010V945454
Colour:	White	Odometer:	40854 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/35 R18	Rear Tyre Size:	255/35 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,935.55	5,382.17	7,553.38	58.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,040.00	1,940.00	1,100.00	36.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,975.55	7,322.17	8,653.38	54.17
Approved Total (Overridden) (S\$)		6,000.00		

Nett Amount (S\$)	15,975.55	6,000.00	9,975.55	62.44
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
Nett Liability (S\$)		6,600.00		

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Ysk Auto Workshop (HQ)
No.1 Kaki Bukit Avenue 6, #01-49 Autobay
Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR -LH	Dented	1,736.30 FL	*1,328.00 FL
2	1		*REAR DOOR GLASS OUTER MOULDING	Not Necessary	181.20 FL	*- FL
3	1		*REAR DOOR GLASS RUN CHANNEL	Not Necessary	221.60 FL	*- FL
4	1		*REAR DOOR 1/4 GLASS RUBBER	Not Necessary	89.95 FL	*- FL
5	1		*REAR DOOR INSULATION	Not Necessary	130.20 FL	*- FL
6	1		*REAR DOOR W/STRIP	Necessary	211.63 FL	*211.63 FL
7	1		*REAR FENDER -LH	Repair	1,831.90 FL	*- FL
8	1		*REAR SPORT WHEEL -LH	Cut	2,745.03 FS	*1,000.00 FS
9	1		*REAR SHOCK ABSORBER -LH	Damaged	441.50 FL	*441.50 FL
10	1		*REAR TOP ARM	Bent	280.60 FL	*280.60 FL
11	1		*REAR TOP GUIDE SUPPORT	Bent	291.30 FL	*291.30 FL
12	1		*REAR LOWER ARM	Bent	260.90 FL	*260.90 FL
13	1		*REAR KNUCKLE ARM	Damaged	1,150.60 FL	*952.00 FL
14	1		*REAR WHEEL HUB BEARING	Necessary	461.50 FL	*461.50 FL
15	1		*REAR ANTI ROLL BAR	Not Necessary	435.50 FL	*- FL
16	1		*REAR ANTI ROLL BAR LINK	Not Necessary	89.65 FL	*- FL
17	1		*FRONT DOOR -LH	Repair	1,839.30 FL	*- FL
18	1		*SIDE SILL PANEL GARNISH -LH	Cracked	641.65 FL	*641.65 FL
19	1		*REAR TYRE -LH	Not Necessary	350.00 FS	*- FS
20	1		*SET REAR DOOR 1/4 GLASS SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,450.31	5,869.08
- List Item Discount on L Items 5.00/10.00% (\$)	514.76	486.91
Total Parts (\$)	12,935.55	5,382.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIX REAR UNDERCARRIAGE	New	400.00	220.00
2	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
3	TO RESPRAY UNDERCOATING	New	120.00	40.00
4	TO RESPRAY PAINTING AND ETC	New	1,200.00	1,000.00
5	PANEL BEATING, CUT,WELD REMOVE & REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (S\$)			3,040.00	1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >