

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20014155/KBA3Q2
Date: 28/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900140205
Claimant Vehicle No :	SHD9278R	Insured Vehicle No :	SMN1568U
Date of Loss:	14/12/2020	Nature of Claim:	TP
		Claim No:	2768791221SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9278R		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B79724
Reg. Date:	04/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU603077257
Colour:	Metallic Pearl White/Red	Odometer:	203199 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 7 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,609.97	2,374.05	7,235.92	75.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,290.00	1,190.00	9,100.00	88.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,899.97	3,564.05	16,335.92	82.09
+ GST 7.00/7.00% (S\$)	1,393.00	249.48	1,143.52	82.09

Nett Amount (S\$)	21,292.97	3,813.53	17,479.44	82.09
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$96.30/day) (S\$)		288.90		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,259.88		
Global Sum Settlement (S\$)		4,200.00		

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 15/12/2020

Estimated Period of Repair: 2.5 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Buckled / Distorted	442.60 FL	*442.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Serviceable	332.70 FL	*- FL
3	1		*GUARD ,REAR BUMPER ,CENTER	Dented / Cut	576.30 FL	*576.30 FL
4	1		*COVER ,REAR BUMPER ,LOWER	Dented	15.40 FL	*15.40 FL
5	1		*RETAINER ,REAR BUMPER SIDE ,LH	Serviceable	116.50 FL	*- FL
6	1		*FILLER ,REAR BUMPER EXTENSION ,LH	Serviceable	123.70 FL	*- FL
7	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Distorted	123.70 FL	*123.70 FL
8	1		*SELA ,REAR BUMPER SIDE ,LH	Serviceable	88.50 FL	*- FL
9	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Cracked	451.80 FL	*451.80 FL
10	1		*LENS AND BODY ,REAR LAMP ,RH	Cracked	502.00 FL	*502.00 FL
11	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
12	1		*PANEL SUB-ASSY ,QUARTER ,RH	Repair	871.50 FL	*- FL
13	1		*LINER ,REAR WHEEL HOUSE ,RH	Repair	139.80 FL	*- FL
14	1		*PANEL SUB-ASSY ,BACK DOOR	Repair	1,147.80 FL	*- FL
15	1		*GARNISH SUB-ASSY ,BACK DOOR ,OUTSIDE	Mtg Cracked	925.60 FL	*925.60 FL
16	1		*WEATHERSTRIP ,BACK DOOR	Serviceable	372.30 FL	*- FL
17	1		*SPOILER ,SUB ASSY ,REAR	Serviceable	1,575.40 FL	*- FL
18	1		*STAY ASSY ,BACK DOOR ,LH	Serviceable	242.50 FL	*- FL
19	1		*STAY ASSY ,BACK DOOR ,RH	Serviceable	242.50 FL	*- FL
20	1		*HINGE ASSY ,BACK DOOR ,LH	Repair	61.00 FL	*- FL
21	1		*HINGE ASSY ,BACK DOOR ,RH	Repair	61.00 FL	*- FL
22	1		*COVER FLOOR UNDER NO.1 (LH)	Serviceable	175.10 FL	*- FL
23	1		*COVER FLOOR UNDER NO.2 (LH)	Serviceable	241.90 FL	*- FL
24	1		*COVER ,REAR FLOOR (CTR)	Serviceable	229.90 FL	*- FL
25	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
26	1		*SET REAR BUMPER CLIP	Necessary	95.00 FS	*66.00 FS
27	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
28	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS
29	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS
30	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.90 FS	*- FS
31	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	54.60 FS	*- FS
32	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	54.60 FS	*- FS
33	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
34	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
35	1		*REAR BUMPER PROTECTOR	Not Necessary	180.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET REAR FENDE LINER CLIP	Not Necessary	85.00 FS	*- FS
37	1		*SET REAR BUMPER RETAINER CLIP	Not Necessary	85.00 FS	*- FS
38	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	140.00 FS	*- FS
39	1		*SET TAILLAMP LOWER CLIP	Necessary	55.00 FS	*15.00 FS
40	1		*SET TAILLAMP UPPER CLIP	Necessary	55.00 FS	*15.00 FS
41	1		*END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
42	1		*REAR SPOILER CLIP	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,037.60	3,133.40
- List Item Discount on L Items 25.00/25.00% (\$)	2,427.63	759.35
Total Parts (\$)	9,609.97	2,374.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIT REAR BIG AND SMALL W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,200.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	180.00	0.00
6	TO REMOVE AND REFIT ELECTRICAL WIRING BATTERY AND OTHER NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	New	480.00	0.00
7	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	480.00	0.00
8	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT VACUUM AND CHARGE-IN -GAS	New	380.00	0.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREA	New	250.00	0.00
12	TOWING FEES	New	150.00	0.00
13	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,200.00	660.00
14	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
15	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
16	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
17	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	220.00	0.00
18	TO REPLACE ,REFIX AND TOP UP COOLANT FOR RADIATOR	New	170.00	0.00
19	TO LIFT-UP /OUT ENGINE WITH GEAR BOX AND REFIT	New	440.00	0.00
20	TO REMOVE AND REFIT RADIATOR SUPPORT CROSS -MEMBER AND OTHER NECESSARY ITEMS TO ENABLE BODYWORK REPAIR	New	380.00	0.00
21	TO CONDUCT AND PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC CHECK AND RESET VEHICLE WARNING INDICATORS	New	380.00	0.00
Gross Labour Cost (S\$)			10,290.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >