

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20014156/KPA3Q2
Date: 18/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070061947
Claimant Vehicle No :	SHD5825M	Insured Vehicle No :	GBF8748T
Date of Loss:	12/12/2020	Nature of Claim:	TP
		Claim No:	2121518817SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5825M		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B58184
Reg. Date:	01/11/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU903074966
Colour:	Metallic Pearl White/Red	Odometer:	258536 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,838.05	1,684.50	1,153.55	40.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	870.00	3,550.00	80.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,258.05	2,554.50	4,703.55	64.80
+ GST 7.00/7.00% (S\$)	508.06	178.82	329.24	64.80

Nett Amount (S\$)	7,766.11	2,733.32	5,032.79	64.80
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$112.35/day) (S\$)		224.70		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,065.47		

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*HOOD SUB-ASSY	Bent	983.10 FL	*983.10 FL	
2	1		*HINGE ASSY ,HOOD ,LH	Repair	58.90 FL	*- FL	
3	1		*HINGE ASSY ,HOOD ,RH	Repair	58.90 FL	*- FL	
4	1		*COVER ,FRONT BUMPER	Buckled	516.00 FL	*516.00 FL	
5	1		*REINFORCEMENT SUB-ASSY ,FRONT BUMPER	Serviceable	716.60 FL	*- FL	
6	1		*REINFORCEMENT ,FRONT BUMPER ,NO.2	Serviceable	246.10 FL	*- FL	
7	1		*BRACKET ,FRONT BUMPER SIDE ,LH	Serviceable	59.30 FL	*- FL	
8	1		*BRACKET ,FRONT BUMPER SIDE ,RH	Serviceable	59.30 FL	*- FL	
9	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL	
10	1		*ABSORBER ,FRONT BUMPER LOWER	Serviceable	132.70 FL	*- FL	
11	1		*EMBLEM ASSY ,RADIATOR GRILLE	Dented	90.80 FL	*90.80 FL	
12	1		*GRILLE SUB-ASSY ,RADIATOR	Distorted	346.00 FL	*346.00 FL	
13	1		*GRILLE RADIATOR ,LOWER NO.1	Distorted	170.10 FL	*170.10 FL	
14	1		*FRT NUMBER PLATE WITH HOLDER	Dented	120.00 FS	*45.00 FS	
15	1		*SET FRT BUMPER CLIP	Necessary	80.00 FS	*60.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	3,717.40	2,211.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	879.35	526.50
					Total Parts (\$\$)	2,838.05	1,684.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,600.00	400.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	440.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			4,420.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >