



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 7170B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT DOOR LH	DENTED	1,999.60	1,650.00
1	FRT DOOR OUTER MOULDING LH	NOT NECESSARY	200.97	-
1	FRT DOOR GLASS CHANNEL LH	NOT NECESSARY	233.60	-
1	FRT DOOR RUBBER	NECESSARY	202.00	202.00
	LESS 10% DISCOUNT		-263.62	-185.20
			2,372.55	1,666.80
	<u>LABOUR</u>			
	TO REMOVE AND REFIT DOOR TRIM.		80.00	40.00
	TO SPRAY UNDERSEAL.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT DOOR GLASS.		100.00	40.00
	TO SPRAY PAINTING.		600.00	250.00
	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS,AND FOR CUTTING/WELDING WORKS.		500.00	250.00
			1,360.00	580.00
	GRAND TOTAL		3,732.55	2,246.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00

Report Ref No. CS/AGI20014164/Avf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.