

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20014165/KTF3Q2

Date: 09/02/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001489264

Claimant
Vehicle No : SJW422B

Insured Vehicle No : GZ3865G

Date of Loss: 13/12/2020

Nature of Claim: TP

Claim No: 251002

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW422B**

Make & Model: BMW Z4, 2.5 L SDRIVE 23i ABS D/AB 2WD HID (A)

Engine No: 76274545N52B25AF

Reg. Date: 04/11/2009 (Man. Year: 2009)

Chassis No: WBALM32040E355012

Colour: White

Odometer: 102253 km

Engine Capacity: 2497 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18

Rear Tyre Size:

255/35ZR18

Front Left Side: Michelin 8 mm

Rear Left Side:

Michelin 8 mm

Front Right Side: Michelin 8 mm

Rear Right Side:

Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,876.05	4,203.64	2,672.41	38.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,710.00	1,100.00	1,610.00	59.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,586.05	5,303.64	4,282.41	44.67
Approved Total (Overridden) (S\$)		4,250.00		
Nett Amount (S\$)	9,586.05	4,250.00	5,336.05	55.66

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020 Inspected At:

Lim Yew Boo Spray Paint Co (HQ)
Blk 10 Sin Ming Industrial Estate, #01-10
Singapore 575645

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2021)
Parts:	M1-COUPE	BMW Z4 2.5 L SDRIVE 23I ABS D/AB 2WD HID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJW422B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Bent	2,238.20 F	*2,238.20 FN
2	2		*REAR LID ABSORBER	Serviceable	237.40 F	*- FN
3	1		*REAR TAILLAMP/LH	Serviceable	430.00 F	*- FN
4	1		*REAR EMBLEM LOGO BMW	Necessary	81.60 F	*81.60 FN
5	1		*REAR EMBLEM Z4	Necessary	71.60 F	*71.60 FN
6	1		*REAR EMBLEM RED BLUE STRIP	Necessary	69.50 F	*69.50 FN
7	1		*REAR BUMPER	Buckled/Dented	1,536.80 F	*1,218.10 FN
8	2		*REAR BUMPER RETAINER	Serviceable	170.40 F	*- FN
9	1		*REAR BUMPER BEAM	Repair	775.95 F	*- FN
10	4		*REAR BUMPER CLIPS	Necessary	22.00 F	*22.00 FN
11	1		*REAR REVERSE PDC SENSOR (4 Pcs)	Shorted (2 Pcs only)	952.20 F	*476.10 FN
12	4		*REAR REVERSE PDC SENSOR HOLDER	Necessary	140.40 FS	*140.40 FS
13	1		*REAR NO PLATE (EMBOSS) }	Dented	35.00 FS	*45.00 FS
14	1		*REAR NO PLATE HOLDER }	Dented	35.00 FS	*- FS
15	1		*REAR SPOILER SEALANT	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	6,876.05	4,412.50
- Nett Item Discount on N Items 0.00/5.00% (\$\$)	0.00	208.86
Total Parts (\$\$)	6,876.05	4,203.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS	New	120.00	30.00
2	TO CHECK & ALIGN ON AFFECTED EXHAUST	New	150.00	60.00
3	LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS	New	80.00	0.00
4	TO CHECK WATER SEEPAGE	New	60.00	0.00
5	LABOUR TO CHECK & ALIGN ON CONVERTIBLE TOP & WIRING OF CONVERTIBLE FUNCTION	New	150.00	60.00
6	TO RE-SET ABS SYSTEM & ERASE REGISTERED FAULT	New	150.00	100.00
7	TO REPAIR,PANEL BEAT & ALIGN ON REAR AFFECTED END PANEL & LABOUR TO REPLACE THE ABOVE PARTS	New	900.00	350.00
8	TO PUTTY,PRIMER & SPRAY PAINT ON REAR BOOT LID,REAR BUMPER,REAR END PANEL & REAR REVERSE SENSOR X4 PCS USING 2K PAINT	New	1,100.00	500.00
Gross Labour Cost (S\$)			2,710.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >