

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20014172/APS3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993812
Claimant Vehicle No :	SKD2586L	Insured Vehicle No :	GBJ2403G
Date of Loss:	16/12/2020	Nature of Claim:	TP
		Claim No:	7989287780SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD2586L	Engine No:	1NZY436156
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305281250
Reg. Date:	14/11/2011 (Man. Year: 2011)	Odometer:	21732 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,690.32	4,460.00	2,230.32	33.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,480.00	1,950.00	1,530.00	43.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,170.32	6,410.00	3,760.32	36.97
Approved Total (Overridden) (S\$)		5,000.00		

(S\$)	10,170.32	5,000.00	5,170.32	50.84
+ GST 7.00/7.00% (S\$)	711.92	350.00	361.92	50.84
Nett Amount (S\$)	10,882.24	5,350.00	5,532.24	50.84
+ Loss of Use (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		6,357.49		
Global Sum Settlement (S\$)		6,350.00		

INSPECTION

Date of Assignment: 18/12/2020

Date Inspected: 18/12/2020

Estimated Period of Repair: 7.0 days

Inspected At:

Kang Car Repairers Pte Ltd (HQ)
 No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Distorted	784.30 FL	*784.30 FL
2	1		*BOOT LID LOGO	Necessary	50.20 FL	*50.20 FL
3	1		*BOOT LID VIOS EMBLEM	Necessary	43.60 FL	*43.60 FL
4	1		*BOOT LID E EMBLEM	Necessary	38.60 FL	*38.60 FL
5	2		*BOOTLID HINGE	Not Necessary	197.60 FL	*- FL
6	1		*BOOT LID GARNISH	Cracked	168.90 FL	*168.90 FL
7	2		*REAR NUMBER PLATE LAMP	Not Necessary	137.20 FL	*- FL
8	1		*BOOTLID KEY LOCK	Not Necessary	128.90 FL	*- FL
9	1		*BOOT LID INNER LOCK	Damaged	298.80 FL	*298.80 FL
10	1		*BOOT LID INNER LOCK STRIKER	Not Necessary	28.60 FL	*- FL
11	1		*BOOTLID RUBBER	Cut	166.40 FL	*166.40 FL
12	1		*REAR FENDER TRIM RH	Not Necessary	355.90 FL	*- FL
13	1		*REAR FENDER MUDFLAP RH	Not Necessary	69.30 FL	*- FL
14	1		*REAR FENDER TRIM LH	Not Necessary	355.90 FL	*- FL
15	1		*TAIL LAMP -RH	Cracked	357.90 FL	*357.90 FL
16	1		*TAIL LAMP PANEL RH	Dented	162.40 FL	*162.40 FL
17	1		*TAIL LAMP LH	Cut	357.90 FL	*357.90 FL
18	1		*TAIL LAMP PANEL LH	Not Necessary	162.40 FL	*- FL
19	1		*REAR PANEL	Distorted	680.10 FL	*680.10 FL
20	1		*REAR PANEL TRIM	Deformed	242.10 FL	*242.10 FL
21	1		*SPARE TYRE COVER	Cut	206.90 FL	*206.90 FL
22	1		*REAR SPARE TYRE PANEL RH SPONGE	Deformed	245.20 FL	*245.20 FL
23	1		*SPARE TYRE PANEL LH SPONGE	Deformed	245.20 FL	*245.20 FL
24	1		*SPARE TYRE PANEL INNER SPONGE	Not Necessary	246.30 FL	*- FL
25	1		*REAR BUMPER	Distorted	482.30 FL	*482.30 FL
26	1		*REAR BUMPER BRACKET	O/S Bent	152.00 FL	*76.00 FL
27	2		*REAR BUMPER SIDE RETAINER	Necessary	193.40 FL	*193.40 FL
28	2		*REAR BUMPER RETAINER (SMALL)	Not Necessary	147.20 FL	*- FL
29	1		*REAR BUMPER REFLECTOR -RH	Cracked	99.80 FL	*99.80 FL
30	1		*EXHAUSY PIPE	Not Necessary	683.40 FL	*- FL
31	2		*EXHAUST PIPE MOUNTING	Not Necessary	38.40 FL	*- FL
32	1		*BOOT LID NUMBER 285 STICKER	Necessary	35.00 FS	*35.00 FS
33	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
34	1		*SET REAR FENDER TRIM CLIPS RH	Not Necessary	60.00 FS	*- FS
35	1		*SET REAR FENDER MUDFLAP CLIPS RH	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FENDER STICKER RH	Necessary	290.00 FS	*290.00 FS
37	1		*SET REAR FENDER TRIM CLIPS LH	Not Necessary	60.00 FS	*- FS
38	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*20.00 FS
39	2		*L PLATE BRACKET	Necessary	70.00 FS	*50.00 FS
40	1		*L PLATE	Bent	80.00 FS	*50.00 FS
41	1		*SET REAR BUMPER STICKER	Necessary	280.00 FS	*280.00 FS
42	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,572.10	5,685.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,881.78	1,225.00
Total Parts (\$)	6,690.32	4,460.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIX REAR EXHAUST PIPE	New	150.00	0.00
3	TO REPLACE STICKERS	New	80.00	0.00
4	TO REMOVE AND REFIT REAR INNER TRIM	New	100.00	60.00
5	TO SPRAY UNDERSEAL	New	100.00	60.00
6	(REAR) TO SPRAY PAINTING	New	1,500.00	800.00
7	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			3,480.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >