

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20014174/KGS3Q2
Date: 07/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900036633
Claimant Vehicle No :	SKW4853C	Insured Vehicle No :	SBT5515U
Date of Loss:	18/12/2020	Nature of Claim:	TP
		Claim No:	7687823859SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW4853C	Engine No:	P520326974
Make & Model:	MAZDA 3, 1.5 4 DOOR SEDAN SP (A)	Chassis No:	JM6BM42A8G0322466
Reg. Date:	30/10/2015 (Man. Year: 2015)	Odometer:	97687 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,674.40	906.40	768.00	45.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	1,170.00	450.00	27.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,294.40	2,076.40	1,218.00	36.97
Approved Total (Overridden) (S\$)		1,650.00		

(S\$)	3,294.40	1,650.00	1,644.40	49.92
+ GST 7.00/7.00% (S\$)	230.61	115.50	115.11	49.92
Nett Amount (S\$)	3,525.01	1,765.50	1,759.51	49.92
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
Nett Liability (S\$)		1,965.50		

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun Industrial Park A
 Singapore 768761

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH DOOR	Bent	1,060.00 FL	*1,060.00 FL
2	1		*SET FRONT LH DOOR FRAME STICKER	Necessary	73.00 FL	*73.00 FL
3	1		*LH ROCKER PANEL	Repair	960.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$)	
					2,093.00	1,133.00
					- List Item Discount on L Items 20.00/20.00% (\$)	
					418.60	226.60
					Total Parts (\$)	
					1,674.40	906.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT LH DOOR & ATTACHMENTS TO CUT ,WELD & RENEW LH ROCKER PANEL ,KNOCKING & REPAIR LH CENTRE PILLAR & REALIGN THE SAME	New	600.00	400.00
2	PUTTY & RESPRAY FRT LH DOOR ,FRT LH FENDER ,LH ROCKER PANEL ,LH CENTRE PILLAR & ALL AFFECTED AREAS	New	800.00	600.00
3	REMOVE & REFIX FRT LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	New	60.00	60.00
4	REMOVE & REFIX FRT SEAT ,CARPET & GARNISH TO FACILITATE REPAIR	New	100.00	80.00
5	RUSTPROOFING	New	60.00	30.00
Gross Labour Cost (\$)			1,620.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >