

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014180/AVD3Q2

Date: 05/02/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCNSA00002211900	
Claimant Vehicle No : SLC9219U	Insured Vehicle No : SKD6477S	
Date of Loss: 17/12/2020	Nature of Claim: TP	Claim No: SNM20D204931/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLC9219U		
Make & Model: KIA FORTE K3, 1.6 (A)	Engine No: G4FGGH613282	
Reg. Date: 30/05/2016 (Man. Year: 2016)	Chassis No: KNAFX411MG5603827	
Colour: Grey	Odometer: 77150 km	
Engine Capacity: 1591 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16	Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm	Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm	Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,384.27	6,077.09	7,307.18	54.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	2,090.00	1,340.00	39.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,814.27	8,167.09	8,647.18	51.43
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	16,814.27	6,500.00	10,314.27	61.34

INSPECTION

Date of Assignment: 01/02/2021		
Date Inspected: 21/12/2020	Inspected At:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair: 7.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2021)
Parts:	143	KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9219U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	763.00 FL	*688.00 FL
2	1		*REAR BUMPER BRACKET	Not Necessary	107.00 FL	*- FL
3	1		*REAR BUMPER RETAINER	Necessary	116.00 FL	*116.00 FL
4	1		*REAR BUMPER REINFORCEMENT UPPER BRACKET	Damaged	86.20 FL	*45.00 FL
5	1		*REAR BUMPER REINFORCEMENT LOWER BRACKET	Damaged	76.50 FL	*45.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Cracked	362.00 FL	*362.00 FL
7	1		*REAR BUMPER LOWER SPOILER	Deformed	1,200.00 FL	*384.00 FL
8	2		*REAR BUMPER BRACKET R/L	Dented	112.80 FL	*112.80 FL
9	1		*REAR BUMPER SPONGE	Not Necessary	176.20 FL	*- FL
10	2		*REAR BUMPER MUDFLAP R/L	Not Necessary	124.60 FL	*- FL
11	1		*REAR BOOTLID ASSY	Distorted	962.40 FL	*962.40 FL
12	1		*REAR BOOTLID WEATHERSTRIP	Cut	186.00 FL	*186.00 FL
13	1		*REAR BOOTLID CENTRE LOGO	Necessary	68.00 FL	*68.00 FL
14	1		*REAR BOOTLID CERATO EMBLEM	Necessary	66.00 FL	*66.00 FL
15	1		*REAR BOOTLID CYCLE AND CARRIAGE EMBLEM	Necessary	48.00 FL	*48.00 FL
16	1		*REAR BOOTLID LOCK MECHANISM	Damaged	126.00 FL	*126.00 FL
17	1		*REAR BOOTLID LOCK CATCH	Not Necessary	66.00 FL	*- FL
18	2		*REAR BOOTLID TAIL LAMP R/L	Cut	646.00 FL	*646.00 FL
19	2		*REAR BOOTLID HINGE R/L	Not Necessary	157.20 FL	*- FL
20	1		*REAR BOOTLID OUTER GARNISH	Not Necessary	178.00 FL	*- FL
21	1		*REAR BOOTLID INNER BOARD	Not Necessary	179.00 FL	*- FL
22	2		*REAR TAIL LAMP R/L	Cut	1,254.00 FL	*1,254.00 FL
23	1		*REAR WHEEL PANEL TOP BOARD	Deformed	267.90 FL	*267.90 FL
24	1		*REAR CHASSIS EXTENSION L/H	Repair	1,287.00 FL	*- FL
25	1		*REAR WHEEL PANEL	Repair	1,297.00 FL	*- FL
26	1		*REAR END LOWER PANEL	Dented	802.00 FL	*498.00 FL
27	1		*REAR END LOWER PANEL TOP GARNISH	Deformed	127.00 FL	*127.00 FL
28	1		*REAR NO PLATE LAMP	Not Necessary	120.00 FL	*- FL
29	1		*REAR EXHAUST PIPE	Not Necessary	862.30 FL	*- FL
30	1		*REAR EXHAUST PIPE GASKER	Not Necessary	64.30 FL	*- FL
31	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	76.20 FL	*- FL
32	1		*REAR EXHAUST PIPE HEAT SHIELD		115.60 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Not Necessary		
33	1		*CENTER EXHAUST PIPE	Not Necessary	752.10 FL	*- FL
34	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
35	10		*REAR BUMPER LOWER SPOILER CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*REAR BUMPER LOWER SPOILER SEALANT	Not Necessary	80.00 FS	*- FS
37	2		*REAR BUMPER REFLECTOR R/L	Cut	275.20 FS	*275.20 FS
38	4		*REAR BOOTLID OUTER GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
39	8		*REAR BOOTLID INNER BOARD CLIPS	Not Necessary	40.00 FS	*- FS
40	1		*REAR END LOWER PANEL SEALANT	Necessary	120.00 FS	*60.00 FS
41	4		*REAR END LOWER PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
42	1		*REAR BUMPER REVERSE SENSOR	Damaged	880.00 FS	*200.00 FS
43	1		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	250.00 FS	*50.00 FS
44	1		*REAR NO PLATE	Bent	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,667.50	6,677.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,283.23	600.21
Total Parts (\$\$)	13,384.27	6,077.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR FOR PANEL BEATING	New	1,500.00	1,000.00
2	TO PUTTY & SPRAY PAINTING REAR PORTION	New	1,500.00	800.00
3	TO CHECK REAR LIGHTING & WIRING	New	50.00	30.00
4	TO REMOVE AND INSTALL REAR BOOTLID LOCK MECHANISM	New	80.00	80.00
5	TO REMOVE & INSTALL REAR INNER GARNISH TO FACILITATE THE REPAIR	New	120.00	60.00
6	TO APPLY ANTI-RUSH PROOFING TO REAR AFFECTED AREAS	New	120.00	60.00
7	TO REMOVE & INSTALL REAR BUMPER REVERSE SENSOR	New	60.00	60.00
Gross Labour Cost (S\$)			3,430.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >