5/3/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC6/AIG20014183/APS3Q2

Date:

03/05/2021

**REFERENCE** 

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800115039

Claimant Vehicle No :

SKA2226S

Insured Vehicle No:

SME3887H

Date of Loss:

10/11/2020

Nature of Claim:

TP

Claim No: 36849

3684940386SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

Reg. Date:

**SKA2226S** 

Make & Model:

TOYOTA VIOS, 1.5 E (A)

30/09/2019 (Man. Year: 2019)

Engine No: Chassis No: Odometer: 2NR5393167 MR2B23F3101189251

26003 km

Colour:

Bronze 1496 cc

Engine Capacity:
Market Value/New Car Price:

1496 N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No

Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: Front Left Side: Front Right Side: 185/60 R15 Dunlop 6 mm Dunlop 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 185/60 R15 Dunlop 6 mm Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		500.00	200.00	300.00	60.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	500.00	200.00	300.00	60.00
	+ GST 7.00/7.00% (S\$)	35.00	14.00	21.00	60.00
	Nett Amount (S\$)	535.00	214.00	321.00	60.00
	+ Loss of Use (2.0 x	S\$60.00/day) (S\$)	120.00		

(S\$) 334.00

Liable Amount (50.00%) (S\$) 167.00 + Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 169.00

**INSPECTION** 

Date of Assignment:

16/12/2020

Success United Pte Ltd (HQ)

Date Inspected:

16/12/2020 Inspected At:

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Estimated Period of Repair:

2.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen\_printrpt&caseid=977474&extid=351704&CFID=84168466&C... 1/4

ADRIAN LING CHEW HSIAO TONG Adjuster: Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### **REPAIR DETAILS**

# **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
<u>Lab</u>	our Items						
1	REPAIR & RESPRAY PAINTING ON REAR BUMPER & REAR FENDER RH	New	500.00	200.00			
	Gross Labou	r Cost (S\$)	500.00	200.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >