

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20014188/GVF3E2

Date: 29/12/2020

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700079719		
Claimant Vehicle No :	FBP3620H	Insured Vehicle No :	SJM151K		
Date of Loss:	06/12/2020	Nature of Claim:	TP	Claim No:	4046067667SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBP3620H	Engine No:	G3E6E0484066
Make & Model:	YAMAHA SNIPER T150, 150cc	Chassis No:	MH3UG0740K0152402
Reg. Date:	20/03/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	80/90-17	Rear Tyre Size:	120/70-17
Front Left Side:	Maxxis 4 mm	Rear Left Side:	Maxxis 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	21/12/2020		
Date Inspected:	21/12/2020	Inspected At:	Prospin Motorsports 25 KAKI BUKIT ROAD, #03-30 SYNERGY @KB Singapore 417800
Estimated Period of Repair:	2.0 days		

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WING MIRROR	Broken	0.00 F	*- F
2	1		*FRONT LH SIGNAL LAMP	Scratched	0.00 F	*- F
3	1		*FRONT RH SIGNAL LAMP	Cut	0.00 F	*- F
4	1		*HANDLE BAR	Bent	0.00 F	*- F
5	1		*CLUTCH LEVER	Cut	0.00 F	*- F
6	1		*HAND BRAKE LEVER	Cut	0.00 F	*- F
7	2		*SIDE FAIRING	Cut	0.00 F	*- F
8	1		*FAIRING SHIELD	Cut	0.00 F	*- F
9	1		*FOOT BRAKE	Cut	0.00 F	*- F
10	1		*FRONT FOOT REST	Cut	0.00 F	*- F
11	1		*CLUTCH ENGINE COVER	Cut	0.00 F	*- F
12	1		*FOOT GEAR SHIFTER	Bent	0.00 F	*- F
13	1		*REAR FOOT REST	Cut	0.00 F	*- F
14	2		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
15	1		*EXHAUST MUFFLER ASSY	Repair	0.00 F	*- F
16	1		*REAR RH SIGNAL LAMP	Cut	0.00 F	*- F
17	1		*REAR NUMBER PLATE LAMP	Distorted	0.00 F	*- F
18	1		*REAR BOX	Missing	0.00 F	*- F
19	1		*REAR BOX BRACKET	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)

0.00

0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >