

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014193/R1TF3Q2

Date: 01/02/2021

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00098302007
Claimant Vehicle No :	SCF12Z	Insured Vehicle No :	SJC6625Z
Date of Loss:	16/12/2020	Nature of Claim:	TP
		Claim No:	SNM20D204898/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCF12Z		
Make & Model:	NISSAN QASHQAI, 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A)	Engine No:	MR20431846W
Reg. Date:	27/10/2016 (Man. Year: 2016)	Chassis No:	SJNFBAJ11U1784078
Colour:	Red	Odometer:	73174 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R19	Rear Tyre Size:	225/45R19
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,700.02	3,195.46	1,504.56	32.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,763.00	2,043.00	720.00	26.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,463.02	5,238.46	2,224.56	29.81
+ GST 7.00/7.00% (S\$)	522.41	366.69	155.72	29.81
Nett Amount (S\$)	7,985.43	5,605.15	2,380.28	29.81

INSPECTION

Date of Assignment:	21/12/2020	
Date Inspected:	11/01/2021	Inspected At:
		TC AutoClinic Pte Ltd (Lok Yang) 1 SIXTH LOK YANG ROAD Singapore 628099
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2021)
Parts:	M1-SUV	NISSAN QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCF12Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	3		*CLIP-RH REAR OVER FENDER	Necessary	8.10 FN	*8.10 FN
2	3		*CLIP-RH REAR OVER FENDER	Necessary	8.10 FN	*8.10 FN
3	1		*OVER FENDER-REAR,RH	Scratched	540.50 FN	*540.50 FN
4	1		*LH REAR BUMPER STAY	Serviceable	141.00 FN	*- FN
5	1		*RH REAR BUMPER STAY	Serviceable	141.00 FN	*- FN
6	1		*REAR BUMPER REINFORCEMENT	Serviceable	691.50 FN	*- FN
7	1		*REAR BUMPER ENERGY ABSORBER	Serviceable	141.40 FN	*- FN
8	1		*RH REAR BUMPER SIDE BRACKET	Necessary	38.90 FN	*38.90 FN
9	1		*RETAINER-REAR BUMPER SIDE,RH	Serviceable	25.70 FN	*- FN
10	3		*REAR BUMPER UPPER CLIP	Necessary	24.00 FN	*24.00 FN
11	2		*CANOE RIVET-REAR BUMPER	Necessary	14.20 FN	*14.20 FN
12	4		*REAR BUMPER LOWER CLIP	Necessary	5.20 FN	*5.20 FN
13	1		*FINISHER-REAR BUMPER	Serviceable	18.80 FN	*- FN
14	1		*REAR BUMPER FASCIA	Deformed	796.70 FN	*796.70 FN
15	1		*REFLEX REFLECTOR-RH	Serviceable	61.90 FN	*- FN
16	1		*LAMP ASSY-REAR COMBI RH	Serviceable	346.90 FN	*- FN
17	1		*HUB ASSY-REAR AXLE RH	Bent	365.40 FS	*365.40 FS
18	1		*RH REAR SPORTS RIM	Scratched	1,681.50 FS	*1,681.50 FS
19	1		*REVERSE SENSOR (4 EYE)	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	5,300.80	3,482.60
- Nett Item Discount on N Items 20.00/20.00% (S\$)	600.78	287.14
Total Parts (S\$)	4,700.02	3,195.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REPLACE REVERSE SENSOR,NECESSARY ADJUSTMENT & FUNCTION TEST	New	110.00	110.00
2	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION-PASSENGER	New	103.00	103.00
3	REMOVE/INSTALL REAR BUMPER AND AFFECTED PORTION.REPAIR END PANEL AND RH REAR FENDER	New	1,170.00	700.00
4	RESPRAY PAINT REAR BUMPER,END PANEL AND RH REAR FENDER	New	1,100.00	850.00
5	REMOVE/INSTALL RH REAR TYRE AND SPORTS RIM TO FACILITATE THE REPAIR	New	20.00	20.00
6	CHECK REAR LIGHTINGS AND WIRING SYSTEM	New	20.00	20.00
7	REMOVE/INSTALL RH REAR UNDERCARRIAGE MECHANICAL PARTS TO FACILITATE THE REPAIR	New	240.00	240.00
Gross Labour Cost (S\$)			2,763.00	2,043.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >