

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCF12Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	/ /
2	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	103.00	/ /
3	ZZ/001	REMOVE/INSTALL REAR BUMPER AND AFFECTED PORTION. REPAIR END PANEL AND RH REAR FENDER @ 280 X 2.5 RH Side Panel & rear door	1170.00	700 /
4	ZZ/002	RESPRAY PAINT REAR BUMPER, END PANEL AND RH REAR FENDER @ 280 X 3 + RH R.S.M. Panel & rear door	1100.00	750 + 1100 = 850 /
5	ZZ/003	REMOVE/INSTALL RH REAR TYRE AND SPORTS RIM TO FACILITATE THE REPAIR	20.00	/ /
6	ZZ/004	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	/ /
TOTAL LABOUR CHARGES			2523.00	

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCF12Z

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	RH REAR SPORTS RIM <i>SCF</i>	D0300-4ES3B		1681.50
2	CLIP-RH REAR OVER FENDER @\$2.70EACH X3PCS <i>SCF</i>	76847-JG00A	8.10	
3	CLIP-RH REAR OVER FENDER @\$2.70EACH X3PCS <i>SCF</i>	76847-4EA0A	8.10	
4	OVER FENDER-REAR, RH <i>SCF</i>	93828-4EA0A	540.50	
5	LH REAR BUMPER STAY <i>X SCF</i>	H5211-4EAMA	141.00	
6	RH REAR BUMPER STAY <i>X SCF</i>	H5210-4EAMA	141.00	
7	REAR BUMPER REINFORCEMENT <i>X SCF</i>	H5030-4EAMA	691.50	
8	REAR BUMPER ENERGY ABSORBER <i>X SCF</i>	85090-4EA0B	141.40	
9	RH REAR BUMPER SIDE BRACKET <i>SCF</i>	85220-4EA0A	38.90	
10	RETAINER-REAR BUMPER SIDE, RH <i>X SCF</i>	79184-4EA0A	25.70	
11	REVERSE SENSOR(4EYE) <i>? X SCF</i>	SENSOR-4-FUM		250.00
12	REAR BUMPER UPPER CLIP @\$8.00EACH X3PCS <i>SCF</i>	85284-JD00A	24.00	
13	CANOE RIVET-REAR BUMPER @\$7.10EACH X2PCS <i>SCF</i>	76882-0M000	14.20	
14	REAR BUMPER LOWER CLIP @\$1.30EACH X4PCS <i>SCF</i>	01553-05933	5.20	
15	FINISHER-REAR BUMPER <i>X SCF</i>	85071-4EA0A	18.80	
16	REAR BUMPER FASCIA <i>SCF</i>	85022-4EA0H	796.70	
17	REFLEX REFLECTOR-RH <i>X SCF</i>	26560-JJ90A	61.90	
18	LAMP ASSY-REAR COMBI, RH <i>? X SCF</i>	26550-4EA0A	346.90	
SUB TOTAL			3003.90	0.00 1931.50
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			600.78	0.00 0.00
GRAND TOTAL			2403.12	0.00 1931.50
OVERALL TOTAL			4334.62	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
1 SIXTH LOK YANG ROAD
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SCF12Z

TOTAL LABOUR CHARGES	2523.00
TOTAL SPARE PARTS CHARGES	4334.62
GRAND TOTAL	6857.62 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Ren - 1/10/2018
SURVEYED DATE	:	11/01/2021 @ 1075
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 5 days
LIABILITY	:	0.00
REMARKS	:	Resurvey before print

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date