

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20014195/AVD3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : PC4699C

Insured Vehicle No : GBK1254X

Date of Loss: 18/12/2020

Nature of Claim:

TP

Claim No: CDMCG20001944

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC4699C**

Make & Model: TOYOTA HIACE, 2.0 (M)

Engine No: 1KD2588896

Reg. Date: 17/02/2016 (Man. Year: 2015)

Chassis No: JTFHT02P400189375

Colour: Silver

Odometer: 159633 km

Engine Capacity: 2982 cc

Market Value/New Car

Price: N/A

Sum Insured (\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size:

195 R15C

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,189.05	6,015.50	15,173.55	71.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,320.00	2,220.00	3,100.00	58.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	26,509.05	8,235.50	18,273.55	68.93
Approved Total (Overridden) (\$)		6,600.00		
Nett Amount (\$)	26,509.05	6,600.00	19,909.05	75.10

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Jan 2021)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC4699C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,712.45 F	*1,712.45 FL
2	2		*REAR BOOT LID HINGE	Not Necessary	343.40 F	*- FL
3	2		*REAR BOOT LID SHOCK ABSORBER	Not Necessary	748.90 F	*- FL
4	1		*REAR BOOT LID TOYOTA HIACE STICKER	Necessary	57.60 F	*57.60 FL
5	1		*REAR BOOT LID EMBLEM LOGO	Necessary	41.10 F	*41.10 FL
6	1		*REAR BOOT LID CENTRE MOULDING	Deformed	281.90 F	*281.90 FL
7	2		*REAR BOOT LID NUMBER PLATE LAMP	Not Necessary	135.60 F	*- FL
8	1		*REAR BOOT LID INNER LOCK	Damaged	374.25 F	*374.25 FL
9	1		*REAR BOOT LID INNER POWER LOCK	Damaged	276.20 F	*276.20 FL
10	1		*REAR BOOT LID INNER ALUMINIUM PANEL	Not Necessary	1,000.00 FS	*- FS
11	1		*REAR BOOT LID INNER TRIM BOARD	Torn	372.50 F	*165.00 FL
12	1		*REAR BOOT LID WEATHERSTRIP	Cut	381.90 F	*381.90 FL
13	1		*REAR BOOT LID WINDSCREEN	Cut	1,355.00 F	*1,015.00 FL
14	1		*REAR BOOT LID WINDSCREEN SEAL	Necessary	105.00 F	*105.00 FL
15	2		*REAR TAIL LAMP	Cracked	743.00 F	*578.00 FL
16	2		*REAR TAIL LAMP PANEL	Repair	711.60 F	*- FL
17	2		*REAR TAIL LAMP LOWER COVER	Deformed	364.20 F	*140.00 FL
18	2		*REAR TAIL LAMP LOWER COVER RETAINER	Not Necessary	342.90 F	*- FL
19	4		*REAR TAIL LAMP CLIP	Necessary	32.00 F	*32.00 FL
20	2		*REAR FENDER AIR DUCT	Not Necessary	344.90 F	*- FL
21	1		*REAR BUMPER	Deformed	374.45 F	*374.45 FL
22	10		*REAR BUMPER CLIP	Necessary	65.00 F	*30.00 FL
23	2		*REAR BUMPER SIDE RETAINER	Necessary	262.70 F	*262.70 FL
24	1		*REAR END PANEL OUTER	Dented	581.10 F	*581.10 FL
25	1		*REAR END PANEL INNER	Dented	591.25 F	*591.25 FL
26	1		*REAR FLOOR PANEL	Repair	1,850.00 F	*- FL
27	1		*REAR FLOOR PANEL TOP MOULDING	Bent	174.10 F	*174.10 FL
28	8		*REAR FLOOR PANEL TOP MOULDING CLIP	Not Necessary	52.00 F	*- FL
29	1		*REAR FLOOR PANEL CARPET	Not Necessary	750.00 F	*- FL
30	1		*REAR FLOOR PANEL PLYWOOD	Not Necessary	550.00 F	*- FL
31	1		*REAR SPARE TYRE BRACKET	Not Necessary	172.10 F	*- FL
32	1		*REAR EXHAUST	Not Necessary	1,712.85 F	*- FL
33	1		*REAR CENTRE EXHAUST	Not Necessary	1,829.10 F	*- FL
34	1		*REAR CENTER SEAT CUSHION & LEATHER	Not Necessary	700.00 F	*- FL
35	1		*REAR L/H SEAT CUSHION & LEATHER	Not Necessary	700.00 F	*- FL
36	1		*REAR BOOT LID 70KM/H STICKER	Necessary	20.00 FS	*10.00 FS
37	1		*REAR BOOT LID NUMBER PLATE	Bent	50.00 FS	*25.00 FS
38	1		*REAR BOOT LID REVERSE CAMERA	Damaged	680.00 FS	*400.00 FS
39	1		*REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 21,189.05 7,809.00
- List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,793.50

Total Parts (\$\$) 21,189.05 6,015.50

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT TRIMBOARD AND CUSHION	New	800.00	80.00
2	TO REMOVE & REFIT REVERSE SENSOR	New	100.00	60.00
3	TO REMOVE & REFIT REAR WINDSCREEN	New	120.00	120.00
4	GUM	New	50.00	50.00
5	TO CHECK WIRING	New	100.00	30.00
6	TUFF KOTE	New	150.00	80.00
7	PANEL BEATING	New	2,000.00	1,000.00
8	SPRAY PAINTING	New	2,000.00	800.00
Gross Labour Cost (\$\$)			5,320.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >