

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20014202/UVD3Q2

Date: 04/01/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3085681900

**Claimant
Vehicle No :** SGT9839A

**Insured
Vehicle No :** SMP9369P

Date of Loss: 17/12/2020

Nature of Claim: TP

Claim
No: SNM20D204942/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGT9839A**

Make & Model: LEXUS IS, 2.5 250 STD (A)

Engine No: 4GR0668442

Reg. Date: 10/06/2010 (Man. Year: 2010)

Chassis No: JTHBK262202098913

Colour: Purple

Odometer: 120750 km

Engine Capacity: 2500 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18

Rear Tyre Size:

225/40R18

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,150.70	1,346.82	6,803.88	83.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,450.00	1,170.00	1,280.00	52.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,600.70	2,516.82	8,083.88	76.26
Approved Total (Overridden) (S\$)		2,000.00		
(S\$)	10,600.70	2,000.00	8,600.70	81.13
+ GST 7.00/7.00% (S\$)	742.05	140.00	602.05	81.13
Nett Amount (S\$)	11,342.75	2,140.00	9,202.75	81.13

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 22/12/2020 Inspected At:

My Car Consultant Pte Ltd (HQ)
60 Jalan Lam Huat,, Carros Centre
#05-67/68
Singapore 737869

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Dec 2020)
Parts:	143	LEXUS IS 2.5 250 STD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT9839A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn/Warped	854.00 FL	*854.00 FL
2	1		*REAR BUMPER REFLECTOR LH	Not Necessary	154.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER (FRONT)	Bent	102.20 FL	*75.10 FL
4	1		*REAR BUMPER SIDE RETAINER (REAR)	Not Necessary	105.20 FL	*- FL
5	1		*REAR FENDER LH	Repair	1,254.00 FL	*- FL
6	1		*REAR FENDER COWLING LH	Not Necessary	212.00 FL	*- FL
7	1		*SET REAR WINDSCREEN MOULDING	Not Necessary	285.00 FL	*- FL
8	1		*REAR DOOR LH	Repair	1,358.00 FL	*- FL
9	1		*REAR KNUCKLE ARM LH	Not Necessary	798.20 FL	*- FL
10	1		*REAR WHEEL HUB COMPLETE WITH BEARING LH	Not Necessary	845.00 FL	*- FL
11	1		*REAR LOWER CONTROL ARM LH	Not Necessary	378.60 FL	*- FL
12	1		*REAR UPPER CONTROL ARM LH	Not Necessary	190.70 FL	*- FL
13	1		*REAR TRAILING ARM LH	Not Necessary	562.00 FL	*- FL
14	1		*REAR SHOCK ABSORBER LH	Not Necessary	452.70 FL	*- FL
15	2		*TAILLAMP LH	Not Necessary	1,996.00 FL	*- FL
16	1		*REAR SPORT RIM LH 18 INCH	Cut	600.00 FS	*600.00 FS
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
18	1		*SET REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
20	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
21	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
22	1		*TAILAMP CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,537.60	1,579.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,386.90	232.28
Total Parts (\$\$)	8,150.70	1,346.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINTING ON AFFECTED AREAS	New	800.00	500.00
2	PANEL BEATING ON AFFECTED AREAS	New	800.00	600.00
3	TO CHECK ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	150.00	50.00
5	REMOVE AND REFIT REAR WINDSCREEN GLASS	New	150.00	0.00
6	PERFORM REAR LIGHTING WIRING TEST FUNCTION	New	150.00	0.00
7	APPLY ANTI RUST ON AFFECTED AREAS	New	200.00	0.00
8	TRANSFER BOOTLID MECHANISM	New	150.00	0.00
Gross Labour Cost (S\$)			2,450.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >