

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014213/EVD3E2

Date: 01/02/2021

REFERENCE

Insured/Claimant:	KOK YIK KUEN	Policy No:	1800043247		
Date of Loss:	20/12/2020	Nature of Claim:	OD	Claim No:	2606696556SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ3608Z		
Make & Model:	MITSUBISHI ATTRAGE, 1.2 (A)	Engine No:	3A92UGT5902
Reg. Date:	30/04/2018 (Man. Year: 2018)	Chassis No:	MMBSTA13AJH001935
Colour:	Silver	Odometer:	52685 km
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$52,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,725.99	3,366.20	1,359.79	28.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,920.00	4,180.00	1,740.00	29.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,645.99	7,546.20	3,099.79	29.12
+ GST 7.00/7.00% (S\$)	745.22	528.23	216.99	29.12
Nett Amount (S\$)	11,391.21	8,074.43	3,316.78	29.12

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020 Inspected At:

Estimated Period of Repair: 8.0 days

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C & C EMBLEM	Necessary	40.00 FS	*40.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*UNPAINTED BODYKITS	Crushed	1,643.00 FS	*1,643.00 FS
4	1		*PANEL, RR COMB LAMP HSG, RH	Not Necessary	60.00 FL	*- FL
5	1		*LAMP ASSY, COMB, RR RH	Not Necessary	335.00 FL	*- FL
6	1		*FACE, RR BUMPER	Broken	748.00 FL	*748.00 FL
7	1		*BRACKET, RR BUMPER, RH	Broken	28.00 FL	*28.00 FL
8	1		*PANEL, RR END	Dented	425.00 FL	*425.00 FL
9	1		*PANEL, TRUNK LID	Dented	791.00 FL	*791.00 FL
10	1		*WEATHERSTRIP, TRUNK LID	Not Necessary	157.00 FL	*- FL
11	1		*HINGE, TRUNK LID, LH	Not Necessary	203.00 FL	*- FL
12	1		*HINGE, TRUNK LID, RH	Not Necessary	203.00 FL	*- FL
13	1		*STRIKER, TRUNK LID LATCH	Not Necessary	20.00 FL	*- FL
14	1		*LATCH, TRUNK LID	Not Necessary	218.00 FL	*- FL
15	1		*GARNISH, RR END PANEL	Not Necessary	336.00 FL	*- FL
16	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
17	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
18	1		*TRIM, RR END	Crushed	66.00 FL	*66.00 FL
19	1		*BOARD, TRUNK ROOM FLOOR	Not Necessary	195.00 FL	*- FL
20	4		*GROMMET,RR END TRIM (Supplementary)	Necessary	12.00 FL	*12.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,620.00	3,863.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	894.01	496.80
Total Parts (\$\$)	4,725.99	3,366.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER, BOOT, REAR RH TAIL LAMP PANEL & AFFECTED AREA. REPAIR ON REAR RH FENDER	New	2,700.00	1,350.00
2	PAINT WORK ON REAR BUMPER, BOOT, REAR RH FENDER, REAR RH TAIL LAMP PANEL, BODY KIT & END PANEL	New	2,100.00	1,750.00
3	REMOVE & INSTALL REAR PARKING ASSIST FOR FACILITATE REPAIR	New	120.00	120.00
4	REMOVE & INSTALL REAR BOTO COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
5	TO TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL	New	120.00	120.00
6	TO APPLY SEALANT ON AFFECTED AREA	New	80.00	80.00
7	PERFORM RUST PREVENTION	New	80.00	40.00
8	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	REPLACE REAR END PANEL (Supplementary)	New	450.00	450.00
Gross Labour Cost (\$\$)			5,920.00	4,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >