

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20014216/EQD3E2

Date: 26/01/2021

REFERENCE

Insured/Claimant:	ANDREW YAP MING HWEE	Policy No:	2070156197	
Date of Loss:	19/12/2020	Nature of Claim:	OD	Claim No: 6106632106SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMW2051P	Engine No:	3A92UJP3584
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AMH000618
Reg. Date:	09/11/2020 (Man. Year: 2020)	Odometer:	2639 km
Colour:	Blue		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	S\$66,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,383.07	10,054.64	2,328.43	18.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,625.00	8,235.00	390.00	4.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,008.07	18,289.64	2,718.43	12.94
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	20,708.07	17,989.64	2,718.43	13.13
+ GST 7.00/7.00% (S\$)	1,449.56	1,259.27	190.29	13.13
Nett Amount (S\$)	22,157.63	19,248.91	2,908.72	13.13

INSPECTION

Date of Assignment: 21/12/2020

Date Inspected: 21/12/2020 Inspected At:

Cycle & Carriage Automotive Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 15.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
2	1		*FRT NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
3	1		*FACE, FR BUMPER	Broken	703.00 FL	*703.00 FL
4	1		*GRILLE, FR UNDER	Broken	90.00 FL	*90.00 FL
5	1		*BRACKET, FR BUMPER SIDE, RH	Broken	8.00 FL	*8.00 FL
6	1		*GARNISH, FR BUMPER, RH	Cut	44.00 FL	*44.00 FL
7	1		*AIR DAM, SIDE, FR RH	Cut	19.00 FL	*19.00 FL
8	1		*GRILLE ASSY, RADIATOR	Cut	597.00 FL	*597.00 FL
9	1		*MARK, THREE-DIA	Necessary	53.00 FL	*53.00 FL
10	1		*COVER, FR BUMPER	Missing	12.00 FL	*12.00 FL
11	1		*COVER, FR BUMPER GRILLE	Crushed	157.00 FL	*157.00 FL
12	1		*GARNISH, FR BUMPER SIDE	Cut	168.00 FL	*168.00 FL
13	1		*GARNISH, FR BUMPER SIDE	Cut	120.00 FL	*120.00 FL
14	1		*FENDER, FR RH	Dented	428.00 FL	*428.00 FL
15	1		*SHIELD, FR WHEELHOUSE, RH	Torn	98.00 FL	*98.00 FL
16	1		*PANEL ASSY, FR END	Dented	918.00 FL	*918.00 FL
17	1		*PANEL ASSY, FR DOOR, RH	Dented	996.00 FL	*996.00 FL
18	1		*HINGE, FR DOOR, LWR RH	Not Necessary	54.00 FL	*- FL
19	1		*HINGE, FR DOOR, UPR RH	Not Necessary	54.00 FL	*- FL
20	1		*PANEL ASSY, RR DOOR, RH	Dented	831.00 FL	*831.00 FL
21	1		*GARNISH, FR PILLAR, RH	Not Necessary	30.00 FL	*- FL
22	1		*AIR DAM, SIDE, RH	Cut	189.00 FL	*189.00 FL
23	1		*TAPE, FR DOOR SASH, RH	Necessary	29.00 FL	*29.00 FL
24	1		*TAPE, RR DOOR SASH, RH	Necessary	29.00 FL	*29.00 FL
25	1		*MIRROR ASSY, DOOR, RH	Cut	638.00 FL	*638.00 FL
26	1		*HEADLAMP ASSY, RH	Broken	1,697.00 FL	*1,697.00 FL
27	1		*LAMP ASSY, FOG, FR LH	Not Necessary	303.00 FL	*- FL
28	1		*TANK, WINDSHIELD WASHER	Crushed	74.00 FL	*74.00 FL
29	1		*MOTOR, WINDSHIELD WASHER	Not Necessary	139.00 FL	*- FL
30	1		*SHAFT AS, FR AXLE DRIVE, RH	Not Necessary	1,201.00 FL	*- FL
31	1		*HUB ASSY, FR WHEEL	Not Necessary	240.00 FL	*- FL
32	1		*BEARING, FR WHEEL HUB	Not Necessary	121.00 FL	*- FL
33	1		*KNUCKLE, RH	Not Necessary	365.00 FL	*- FL
34	1		*WHEEL, DISC	Cut	598.00 FL	*598.00 FL
35	1		*ARM ASSY, FR SUSP, LWR RH	Bent	278.00 FL	*278.00 FL
36	1		*CROSSMEMBER, FR AXLE, NO.1	Bent	864.00 FL	*864.00 FL
37	1		*STRUT, FR SUSP	Not Necessary	452.00 FL	*- FL
38	1		*GEAR & LINK ASSY, STEERING	Bent	1,444.00 FL	*1,444.00 FL
39	1		*END ASSY, TIE ROD	Bent	52.00 FL	*52.00 FL
40	1		*HOSE, A/C COMPR SUCTION (Supplementary)	Torn	231.00 FL	*231.00 FL
41	1		*BELT, ALTERNATOR & OTHERS (Supplementary)	Torn	79.00 FL	*79.00 FL
42	1		*PANEL, AIR GUIDE, RH (Supplementary)	Broken	14.00 FL	*14.00 FL
43	1		*COMPR & CLUTCH ASSY, A/C (Supplementary)	Bent	1,574.00 FL	*1,574.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	16,061.00	13,052.00
- List Item Discount on L Items 23.00/23.00% (S\$)	3,677.93	2,997.36
Total Parts (S\$)	12,383.07	10,054.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER, FRT FENDER RH, FRT SUPPORT PANEL, FRT DOOR RH, REAR DOOR RH, REPAIR REAR FENDER RH, REAR BUMPER, SIDE SILL RH	New	3,600.00	3,600.00
2	REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR	New	100.00	100.00
3	TOP UP AIRCON GAS	New	80.00	80.00
4	CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM	New	120.00	120.00
5	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
6	SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH, FRT SUPPORT PANEL, FRT DOOR RH, REAR DOOR RH, SIDE SILL RH, REAR FENDER RH, REAR BUMPER	New	3,150.00	2,800.00
7	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS	New	180.00	160.00
8	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS	New	180.00	160.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	RENEW FRT UNDER CARRIAGE	New	450.00	450.00
11	TRANSFER NEW RIM	New	30.00	30.00
12	APPLY FRT RIGHT TYPE	New	360.00	360.00
13	RENEW AIRCON COMPRESSOR UNIT, AIR SUCTION PIPE & BELTING (Supplementary)	New	225.00	225.00
Gross Labour Cost (S\$)			8,625.00	8,235.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >