

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20014217/ETF3E2

**Date:** 09/03/2021

### REFERENCE

Insured/Claimant:	CHEW CHIN SENG	Policy No:	1900007951		
Date of Loss:	20/12/2020	Nature of Claim:	OD	Claim No:	4158278530SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD622D	Engine No:	G4FGJH716014
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5027328
Reg. Date:	23/01/2019 (Man. Year: 2018)	Odometer:	27761 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$73,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,481.20	2,304.80	1,176.40	33.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,820.00	4,020.00	1,800.00	30.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>9,301.20</b>	<b>6,324.80</b>	<b>2,976.40</b>	<b>32.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	651.08	442.74	208.34	32.00
<b>Nett Amount (S\$)</b>	<b>9,952.28</b>	<b>6,767.54</b>	<b>3,184.74</b>	<b>32.00</b>

### INSPECTION

Date of Assignment:	21/12/2020		
Date Inspected:	21/12/2020	Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days		

**Adjuster:** CHEN TSUE YEE

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*PANEL ASSY-FRONT DOOR, RH	Dented	1,277.00 FL	*1,277.00 FL
3	1		*MOULDING ASSY-FR DR FRAME, RH	Necessary	37.00 FL	*37.00 FL
4	1		*W/STRIP ASSY-FR DR BELT O/S RH	Not Necessary	64.00 FL	*- FL
5	1		*GLASS ASSY-FRONT DOOR, RH	Not Necessary	207.00 FL	*- FL
6	1		*PANEL ASSY-FRONT DR MODULE, LH	Not Necessary	241.00 FL	*- FL
7	1		*MOTOR ASSY-FRONT POWER WDW, RH	Not Necessary	362.00 FL	*- FL
8	1		*BLACK TAPE-FR DR RR, RH	Necessary	13.00 FL	*13.00 FL
9	1		*BLACK TAPE-FR DR RR, RH	Necessary	13.00 FL	*13.00 FL
10	1		*PANEL ASSY-REAR DOOR, RH	Dented	1,377.00 FL	*1,377.00 FL
11	1		*W/STRIP ASSY-RR DR BELT O/S RH	Necessary	60.00 FL	*60.00 FL
12	1		*MOULDING ASSY-RR DR FRAME, RH	Necessary	44.00 FL	*44.00 FL
13	1		*FILM-ANTI CHIPPG RH	Necessary	27.00 FL	*27.00 FL
14	1		*MIRROR ASSY-OUTSIDE RR VIEW RH	Not Necessary	559.00 FL	*- FL
15	1		*BLACK TAPE-RR DR FRAME RR OTR	Necessary	8.00 FL	*8.00 FL
					Sub Total (\$\$)	4,339.00 2,876.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	857.80 571.20
					Total Parts (\$\$)	3,481.20 2,304.80

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	RENEW ACCIDENT DAMAGED PARTS ON RH FRONT DOOR, RH MIRROR RH REAR DOOR. REPAIR RH REAR FENDER	New	1,600.00	800.00
2	TRANSFER RH FRONT DOOR GLASS, DOOR TRIM, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL	New	120.00	120.00
3	TRANSFER RH REAR DOOR GLASS, DOOR TRIM, MECHANISM AND OTHERS ATTACHMENT TO NEW DOOR PANEL	New	120.00	120.00
4	PAINT WORK SPRAY RH MIRROR, RH FRONT DOOR, RH REAR DOOR, RH REAR FENDER, RH SIDE SILL AND AFFECTED PORTION ( CLEAR COAT )	New	2,880.00	1,920.00
5	APPLY BODY SEALANT	New	120.00	80.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	PERFORM RUST PREVENTION	New	80.00	80.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
10	SUPPLY RH REAR SPORT RIM	New	400.00	400.00
11	LABOUR TO RENEW RH REAR SPORT RIM INCLUDING BALANCING	New	30.00	30.00
12	REPAIR RH SIDE SILL (Supplementary)	New	200.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,820.00</b>	<b>4,020.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >